

FIELD INSPECTION REPORT

Date of Inspection :		District: Samastipur
Division : RWD Rosera		Length (km): 0.530
Name of the Road: Logh Belahi to Belahi Sada Tola-12		
Scheme/Programme:		MAINTENANCE
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/ No
f)	Contraction Joints provided or not (CC Pavement)	Yes/ No
g)	Compaction of flank/slope & raincuts if any	Yes/ No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/ No
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
16/01/21
(Signature)

NAME: Ravi Prasad Paswan

DESIGNATION: J. E. M/I/21