FIELD INSPECTION REPORT

Date of Inspection:			District: Samstipu		
Division: RWD Rosera			Length (km): 1.49 0		
Name of the Road: LOA7 - TOIL to Salha build (TRack 47)					
Scheme/Programme: MAINTENANCE					
Package No.:			Road Id No.:		
			eted/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance					
Sl. No.		Parameters to	be checked	Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/No				
f)	Contraction Joints provided or not (CC Pavement) Yes/No			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drainag				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furnitu	re -			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance H	istory	at tipperate and the supplier of the supplier		
a)	Status of ATR's & any others				

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement	nt (SRI)
Unsatisfactory (U)	

Mote: - Agreement has been terminaled

JE (Signature)

NAME: Tular Kennel Shar

DESIGNATION: AEBithon