

FIELD INSPECTION REPORT

Date of Inspection : 20.1.21
 Division : Aurangabad
 District : Aurangabad
 Length (km):
 Name of the Road: Koriyari Bus Stand to Kael Khar
 Scheme/Programme: MAINTENANCE
 Package No.:
 Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Informatory Board not standard / is No Maintenance Board, c.c. pavement cracks at some places, No earth work in shoulder No road furniture found.	

Overall Rating :

Satisfactory (S)	☒
Satisfactory but requires Improvement (SRI)	☒
Unsatisfactory (U)	☐

20.1.21
 (Signature)
 AE, DCO

NAME: