

LT SNY

21.1.21

FIELD INSPECTION REPORT

Date of Inspection:	<u>Aurangabad</u>	District:	<u>Aurangabad</u>
Division:	<u>Aurangabad</u>	Length (km):	<u>0.50 km</u>
Name of the Road:	<u>Joura Ahir Bigha to Sanda Belugari Road</u>		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Section condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Construction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SRI/U
b)	Condition of Abutment & Wing walls, Slab in R.C.C. culverts	S/SRI/U
c)	Condition of railings slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 50 m stone. Pavement road markings are provided and maintained	No
4.	Compliance History	<u>Maintenance Board not found.</u>
a)	Status of ATR's & any others	<u>No any Road furniture found.</u>

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

NAME:

AB, Kuntabg
21.1.21