


W T S N G FIELD INSPECTION REPORT

Date of Inspection :	21.1.21	District:	Aurangabad
Division :	Aurangabad	Length (km):	1.50 Km
Name of the Road:	Basti Bansi Bigha to near Kature River.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id.No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		Remarks
1.	Pavement	S	
a)	Road Junction condition	S	S/U
b)	Condition of Surfacing.	S	S/U
c)	Riding Quality	S	S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km. & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History	Maintenance Bond not found.	
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:


 21.1.21
 (Signature)
 AE, Kuthuba