

FIELD INSPECTION REPORT

Date of Inspection:	25/11/21	District:	East Champaran
Division:	Madhubani	Length (km):	5.030 km.
Name of the Road:	Kosi to Dikhowa Road		
Scheme Programme:	MAINTENANCE / MMGSY (CC)	Road Id No:	-
Package No:	-		
Status of the Project:	Ongoing / Completed Under Maintenance		
Work is a case of:	New / Other / Upgradation / Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Grading Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓/No
f)	Contraction Joints provided or not (CC Pavement)	✓/No
g)	Compaction of flank/slope & raincuts if any	✓/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓/SR/U
c)	Condition of railings/slab/approach for Bridges	S/SR/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓/No
4.	Compliance History	
a)	Status of ATR's & any others	- N/A -

Overall Rating

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SR)	-
Unsatisfactory (U)	-

[Signature]
25/11/21
(Signature)

NAME: *Madhusudan Sharma*
DESIGNATION: T.E.