FIELD INSPECTION REPORT

Date of Inspection:		District: SamaSHPUY	
Division: RWD Rosera		Length (km): 0.720	
	sho chou	ok to Pusho	
Scheme/Programme:	MAINTENAN		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

SI No.	Parameters to be checked	Remarks
	Payenent	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	
c)	Riding Quality	S/U
d)	Road Camber	S/V
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	s/sri/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Ycs/No
4,	Gompliance History	
a)	Status of ATR's & any others	1Vo '

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Rom forsa Paper DESIGNATION: J.E. 1811/2