

### Inspection Report For Flood Damage Work

Date:

1 Name of PIUs: (no belgary). 2

2 Name of Block/Road: Baikenthper/ Ichairs Awyum To Khorampur

A For Road

1 Damage Location / Chainage: 200 m to AT 5 m

2 Damage Length: 166m

3 Nature of Damage: Heavy Rain / Flood.

4 Details of Restroration Works:

i. Material being used in Restoration Works: நெர்மே நூக்

ii Equipments / Tools being used in Restoration Works: عو هي محدلعد كمان كا العالم المادان ال

iii Procedure taken up in Restoration Works: Y 🧸

iv Restored Length:

166 m

B For Bridge

NIA

- 1 Damage Location / Chainage:
- 2 Damage Length:
- 3 Nature of Damage:
- 4 Details of Restroration Works:
  - i. Material being used in Restoration Works:
  - ii Equipments / Tools being used in Restoration Works:
  - iii Procedure taken up in Restoration Works:
  - iv Restored Length:

15/9/902. JE AE CONT. OF COM.

EE

Execiative Engineer

Hathua



# गामीण कार्य विभाग

Rural Works Department, Govt. of Bihar

## FLOOD DAMAGED REPAIR (F.D.R.)

STATE :- BIHAR

DISTRICT :- GOPALGANJ

BLOCK :- BAIKUNTHPUR

Khaira Aazam To Khorampur

ESTIMATED COST - RS.

1999600.00 Ps 1864600 =00

SUBMITTED BY :-EXECUTIVE ENGINEER RWD (W) DIVISION GOPALGANJ-2

#### Report

Name of Work

Motorable work of Khaira Aazam To Khorampur

**Estimated Cost** 

:- 1999600.00 Ps 1864600 200

**Total length of Road** 

:- 8.250 km

Description :- The present estimate has been farmed under the supervision of Assistant engineer in accordance with the order of Executive Engineer, RWD, WD Gopalganj-2, letter No. - 1574 dated 18-08-2020. The part of above mentioned road has been damaged due to heavy rain/flood. And due to this damage the transporation has been obstructed. The immediate motorable work is necessary in public interest. Villagers will be benefitted by the completion of this motorable work.

In the estimate there has been a provision of repairing the damaged part of the road & making it motorable by filling brickbats. In the context of post flood scenario there is still the flow of water which prevails through the damaged part of the road. Hence there has been a provision of laying 1 Nos of R.C.C. NP3 1000 MM Dia hume pipe.

In this estimate the rate of raw materials and labour wages has been prepared after the analysis of new rate. This estimate is as per the specifications. The estimate is devoted to technical and administrative acceptance.

Phil 191912020 J.E.

A.E.

C7919/2000

E.E.

### red Estimate For Motorable Work in Road from Khaira Aazam To Khorampur damaged due to Heavy rain/flood for year 2020-2021

Sr.	Items	No.	L (M.)	W (M.)	D (M.)	Qty.	Unit	Rate	Amount
1	Providing brick bats billed in ditches including all cost of labour & material with all complete job.			4 2					
	CH - 200 M to 475 M	1	4.00	1.75	0.60	4.20	M3		
		1	12.00	1.10	1.50	19.80	M3		
		1	261 00 <b>24.00</b>	2.50	1.60	68180 -96.00	M3		
		1	6.00	-2.00	1.80	21.60	M3		
		1	5.00	2,00	1.00	10.00	M3		
	4,2	1	15.00	1.50	1.60	36.00	М3		
		1	20.00	3.00	1.80	108.00	M3		
		1	12.00	5.00	2.10	126.00	М3		
		1	18.00	6.00	2.00	216.00	M3		
		1	7.00	5.50	0.90	34.65	М3		
	1 1 1 1 1 1 1 1	1	15.00	4.00	1.50	-90.00 -98.50	M3		
	- 1	1	22.00	3.00	0.70	46.20	МЗ		
-	) "	1	6.00	2.50	0.30	4.50	М3		
	Less for H.P.	0.79	1.23	1.23	5.00	5.98	M3	24/2-11	1813690=
	2000 101 1111					-806.97		2427.65	1959050.54
2	Providing & laying 1000 MM  Dia NP3 Hume Pipe in single row -do-do- complete job.	2	2.50			751.9] 5.00	M	7444-80 <b>4159.56</b> 1824413:	1372384. 20797.80 1846/81.9
									<del>1979</del> 848.34
	Add 1 % Contigency		- "					827420 Total	<u>/ 8 4 6 / ・ 8 2</u> - <del>19798.48</del> - 1999646.82
		_						Say	· <del>1999600.00</del>

Technically Approved for Ro 18, 457 lee (Rupey Eighten Forty Five Thousand Boeven Hundred) city

RWD Work, Gircle-Siwan