

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: Repair of Restoration of road from R.E. road to Praduman Chapra					
Head: - F.D.R.					
Agency: - Departmental / F.F. RWD (10)					
Div. Chakla					
Date of Measurement: -					
①	9 x 30 x	4.30 + 3.00 + 3.80 + 3.90	0.61 x 0.45 + 0.70		
		4	3		
			-		597.37H
	1 x 28 x	4.30 + 3.00 + 3.80 + 3.90			
		4			
		0.61 + 0.45 + 0.70	=		61.95H
					659.32H
②					
Prov. laying sand filling in breach - other job					
	9 x 30 x	4.30 + 3.80 + 3.90 + 3.00	x 0.10 =		101.25H
		4			
	1 x 28 x	4.30 + 3.80 + 3.90 + 3.00	x 0.10 =		10.50H
		4			
					111.75H
③					
		471 = 55/11			526.96 = 0
					14,68,520 = 0
Verified and found correct					
90M					
29.12.2020					
D.E.					
A. Subhan					
29/12/20					
202					

Continuation