

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- raghunath pandit keghar to chauras pokhar tak

(A) For Road: ✓

1. Damage Location/Chainage :- 0.320km
2. Damage Length :- 0.0065 km
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- brick bats.
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:
  - (iv) Restored Length :- 0.0065 km

(Length = 0.850km)

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE

  
11.1.21  
Signature

(Name of Inspection)

EE

RWD work Division

Muzaffarpur East I

## GENERAL ABSTRACT

Name of Road Ragunath Pandit ke Ghar to Chaupar Pokhar Tak

District Muzaffarpur


Block Bochaha


Division Muzaffarpur East-2


Length of Road (in Km) 0.847 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	1.614
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	1.614
TOTAL COST OF PROJECT IN LACS =		1.614


Say 1.614 Lac.

  
21/12/2020  
JE  
RWD

  
31/1/20  
AE  
RWD

  
31/1/20  
EE  
RWD

Technically Approved for Rs 1.614 Lac.  
(Rupees one lac sixty one thousand only.)

  
SE 16.1.20  
RWD work circle  
muzaffarpur