

(3<sup>rd</sup>)  
Record entry

Name of Work -  
 Situation of work -  
 Agency by which work is executed -  
 Date of measurement -  
 No. and date of agreement -  
 (These four lines should be repeated at the commencement of the measurements relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Manner of economy	Restoration of				
Authorities for Surveying & levelling					
Surveyor	J. N. R.				
Head of FDR					
Agency Departmental					
Streets	Poor Quality and condition of roads.				
Condition of roadside walls - etc.					
1 X	8.00 X (5.5 + 4.5) = 10.840				
1 X	6.00 X 2.00 X 0.30 = 3.600				
1 X	4.80 X 2.00 X 0.38 = 3.651				
1 X	3.60 X 1.25 X 0.37 = 1.531				
1 X	12.20 X 1.25 X 0.39 = 6.921				
1 X	4.60 X 4.50 X 0.37 = 7.041				
1 X	9.50 X 1.30 X 0.350 = 4.321				
2 X	11.84 X 1.25 X 0.33 = 9.771				
1 X	9.45 X 1.10 X 0.320 = 3.331				
1 X	8.25 X 1.30 X 0.33 = 3.521				
1 X	13.52 X 1.25 X 0.32 = 10.821				
	Total = 99.621				
(-9) less for 10% wider = 6)9.96					
	Total = 89.66				
1 X 1.25 A-B	5.11120	5.11120	88.021		
1 X 1.25 B-C				5.11120	
				JF	

Continuation

