

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work- Repair of Restoration of road from SH 74 Daliya Bazar to Bing Tola					
Head- F.D.R.					
Agency:- Departmental / E.F.R.D (W)					
Div. Chakia					
Date of Measurement-					
(1) Prov ⁿ and laying at site					
B/B at with all e/riah					
$1 \times 1.52 \times 3.05 \times 0.30 = 1.39M^3$					
$1 \times 15.24 \times 2.44 \times 0.30 = 11.16M^3$					
$3 \times 3.66 \times 3.66 \times 0.60 = 24.11M^3$					
$1 \times 4.57 \times 1.83 \times 0.60 = 5.02M^3$					
$1 \times 21.34 \times 3.05 \times 0.90 = 58.58M^3$					
$1 \times 0.91 \times 3.05 \times 0.30 = 0.83M^3$					
$1 \times 17.68 \times 3.05 \times 0.60 = 32.35M^3$					
$1 \times 20 \times 2.74 \times 0.60 = 32.88M^3$					
$166.32M^3$					
e/riah - 2147 = 401M ³ R. 3, 57, 156 = 15.83M ³					
(2) Prov ⁿ sand filling in					
found ⁿ trenches					
$1 \times 1.52 \times 3.05 \times 0.100 = 0.46M^3$					
$1 \times 15.24 \times 2.44 \times 0.100 = 3.72M^3$					
$3 \times 3.66 \times 3.66 \times 0.100 = 4.02M^3$					
$1 \times 4.57 \times 1.83 \times 0.100 = 0.84M^3$					
$1 \times 21.34 \times 3.05 \times 0.100 = 6.51M^3$					
$1 \times 0.91 \times 3.05 \times 0.100 = 0.28M^3$					
Continuation					15.83M ³

[illegible]