

| Particulars                               | Details of actual measurement                          |    |    |    | Contents of area     |
|-------------------------------------------|--------------------------------------------------------|----|----|----|----------------------|
|                                           | No.                                                    | L. | B. | D. |                      |
| Name of work                              | Repair of Restoration                                  |    |    |    |                      |
| of road from Tamaris Chandpasa            |                                                        |    |    |    |                      |
| to Harijan Tola                           |                                                        |    |    |    |                      |
| Head:-                                    | F.D.R.                                                 |    |    |    |                      |
| Agency:-                                  | Departmental / E.F. RUD                                |    |    |    |                      |
|                                           | (w) Div. Chakia                                        |    |    |    |                      |
| Date of Measurement:-                     |                                                        |    |    |    |                      |
| ① Prov <sup>n</sup> laying at site B/Bats |                                                        |    |    |    |                      |
| in ditches - all 1/2 ch                   |                                                        |    |    |    |                      |
|                                           | $1 \times 4.00 \times \frac{5.00+6.00}{2} \times 1.00$ |    |    |    | $= 2.20 \text{ HP}$  |
|                                           | $1 \times 4 \times \frac{4.50+5.00}{2} \times 0.80$    |    |    |    | $= 15.20 \text{ HP}$ |
|                                           |                                                        |    |    |    | $37.20 \text{ HP}$   |

|                                         |                                                         |    |          |
|-----------------------------------------|---------------------------------------------------------|----|----------|
| cfr                                     | 2147.40/H                                               | R- | 79883=00 |
| ② Prov <sup>n</sup> laying sand filling |                                                         |    |          |
| in found <sup>n</sup> trenches          |                                                         |    |          |
|                                         | $1 \times 4.00 \times \frac{5.00+6.00}{2} \times 0.100$ |    |          |
|                                         | $1 \times 4.00 \times \frac{4.50+5.00}{2} \times 0.100$ |    |          |
|                                         |                                                         |    |          |
|                                         |                                                         |    |          |
| cfr                                     | 471=55/H                                                | R- | 1933=00  |
| ③ Prov <sup>n</sup> and laying Rec Pipe |                                                         |    |          |
| N/B 1000 mm dia                         |                                                         |    |          |
|                                         | $1 \times 7.50$                                         |    |          |
|                                         |                                                         |    |          |
| cfr                                     | 2096.89/H                                               | R- | 15727=00 |
| ④ Prov <sup>n</sup> and laying Rec Pipe |                                                         |    |          |
| N/B 300 H                               |                                                         |    |          |
|                                         |                                                         |    |          |
|                                         |                                                         |    |          |

Continuation

97543=00

Scanned by CamScanner