

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- Bilash Pary keghar to samadhi school tak

(A) For Road: ✓

1. Damage Location/Chainage :- 0.050km, 0.1950km, 0.220km, 0.280km, 0.350km
2. Damage Length :- 0.0905 km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- brick bats
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works: 0.0905km
 - (iv) Restored Length :- 0.0905 km

0.350km
Length = 0.405 km.

(B) For Bridge: X

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


11.1.21

Signature

(Name of Inspection)

EE

RWD work Division
muzaffarpur East I

GENERAL ABSTRACT

Name of Road Bilas Roy Ke Ghar to Santhi School Tak

District Muzaffarpur


Block Bochaha


Division Muzaffarpur East-2


Length of Road (in Km) 0.405 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	1.512
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	1.512
TOTAL COST OF PROJECT IN LACS =		1.512


554 1.51 Lac


31/12/2020
JE
RWD


31/12/20
AE
RWD


31/12
EE
RWD

Technically Approved for Rs 1.51 Lac
(Rupees one Lac fifty one thousand only.)


16.1.21
SE
RWD work circle
muzaffarpur