

Inspection Report for Flood Damage Work

Date

- 1 Name of PIUs- Gyan Vibhakar
- 2 Name of Block/Road- Katra/Barsoli PWD road to masjid Hote Huye, Barsoli pakhar Hote Huye to mullah sahi ke ghar and Bijali' sai ke ghar etc

A For Road

- 1 Damage Location/Chainage 0.105 km 0.220 km, 0.290 km, 0.750 km
_{0.1089 to 0.281 do 0.3225 to 0.775}
- 2 Damage Length 0.165 km
- 3 Nature of Damage
- 4 Details of Restoration Works-

- i Material being used in Restoration Works- Brick ball & local sand
- ii Equipments/Tools being used in Restoration Works-
- iii Procedure Taken up in Restoration Works-
- iv Restored Length 0.165 km

X B. For Bridge

- 1 Damage Location/Chainage
- 2 Damage Length
- 3 Nature of Damage
- 4 Details of Restoration Works-
 - i Material being used in Restoration Works-
 - ii Equipments/Tools being used in Restoration Works-
 - iii Procedure Taken up in Restoration Works-
 - iv Restored Length

Signature of JE/ AE/ EE

12.20
Signature

(Name of Inspector)

EE

RWD WORK DIVISION
Muzaffarpur Cantt-1

GENERAL ABSTRACT

Name of Road Barari PWD Road to Masjid Hote Huye Barri Pokhar Hote Huye To Gulab sah ke ghar and Bijali
District Roy ke Ghar Tak
Block Muzaffarpur
Division Katra
Length of Road (in Km) Muzaffarpur East-2 0.806 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	47.802 47.025
2	Sand Filling	0.745
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	57.747 47.750
TOTAL COST OF PROJECT IN LACS =		57.747 47.750

say 57.75 lac
47.75 lac

[Signature]
25/11/2020
JE
RWD

[Signature] 25/11/2020
AE
RWD

[Signature]
EE
RWD

Technically approved for Rs 47.75 lac
(Rupees ~~forty seven~~ ^{say} seven lac seventy five thousand only)

[Signature] 12/12/20
SE अधीक्षण अभियंता
ग्रामीण कार्य विभाग
RWD WORK CIRCLE
काय अंचल, मुजफ्फरपुर
muzaffarpur