

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, शेरघाटी

Email ID:-ee.rwd.sherghati@gmail.com

Mob:- 8986915324

पत्रांक 143

शेरघाटी/दिनांक 21.01.21

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, शेरघाटी

सेवा में,

नोडल पदाधिकारी (MR 3054)
ग्रामीण कार्य विभाग
पटना, बिहार


विषय :- नई अनुरक्षण नीति- 2018MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महा तय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुरक्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अध्याचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु :- यथोक्त।

विश्वास भाजन


कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, शेरघाटी

19.1.21

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to December 2020

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	Construction of Rural roads Under MR	New Maintenance Policy-2018 MR (3054) BRRDA PATNA Lt no 45 dt 18-06-2020 Lt no 47 dt 24-06-2020 Lt no 51 dt 20-07-2020 Lt no 61 dt 26-08-2020 Lt no 86 dt 11-12-2020	Nil 98.68070 50.27130 96.72200 93.38900 350.11544	Certified that out of Rs. 689.17844 lakh of grants-in-aid sanctioned during the years 2020-21 in favor of EE, RWD works division Sherghati a sum of Rs 339.06300 lakh has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 350.11544 lakh remaining unutilized at the end of the period under report.
	Total:		689.17844	

2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other caudal formalities have been observed.

3. Physical Progress achieved:-

- Construction of Road Works.
- Construction of CD works.

Paty kr hkh 19/01/2022
Divisional Accounts Officer
R.W.D, works Division

19/1/21
Executive Engineer
R.W.D, works Division Sherghati
19.1.21

OFFICE OF EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION, SHERGHATI

Requisition Format for Scheme Head - MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division:- SHERGHATI

Sl.no.	Package No	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No.& Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Amount Allocated (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	MR-N/19-20-SHERGHATI/05	KURMAUNI PIRASIN Rd - BISHUNPUR	NEA220 00463	16.07.19/3025	1.6	53.1500	32.953	14.45	75MBD/20 20-21	04.02.21	04.02.21	3364	25.00	5.01%	19.77180	19.77180	13.1812	Comp.
2	MR-N/19-20-SHERGHATI/09	G.T. Road to Beeza	10502304026	02.12.19/6295	2.2	67.222	55.567	22.74157	66MBD/20 20-21	15.09.21	15.09.21	2912	25.00	5.01%	0.00000	0.00000	50.567	Comp.
3	MR-N/19-20-SHERGHATI/09	Gaya jila antargat dohbi prkhand ke GT road pipardhpti pokahr se mungeshwar mahadait tola hokar chakla mahadait tola tak sadak nirman	10502303010	02.12.19/6295	3.2	111.776	69.383	34.28054	66MBD/20 20-21	15.09.21	15.09.21	3370	25.00	5.01%	0.00000	0.00000	66.3	Comp.
TOTAL																	130.0482	

Fairly 19/10/2021
Divisional Accounts Officer
Rural Works Department, Works
Division, Sherghati

21/11/21
Executive Engineer
Rural Works Department
Works Division, Sherghati
19.11.21

4380


3380

U/V
mm/
km

2300

1380

File : D:\BUMP NEW DATA\10121422.XIs. Section No.: 76, Egn: test
Name of Customer: KOLESHWARI INFRACONS PVT. LTD., Name of Work/ Road: KARMAUNI PIDASIN RD. TO GISHUNPUR



[Signature]
11/12/20
J.E.

[Signature]
11.12.20
H.C.

[Signature]
15/12/20

CONT. NAME:-KOLESHWARI INFRACONS PVT.LTD.

ROAD NAME:- KARMAUNI PIDASIN RD. TO BISHUNPUR

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	TEGORY ROAD	Latitude	Longitude	Event
10/12/20	14:14:0	76	0.1	240	0	2400	2872	G	24.595497	84.947558	Normal
10/12/20	14:15:0	76	0.1	290	10.1	2900	3364	G	24.595473	84.94845	Normal
10/12/20	14:15:0	76	0.1	300	10.1	3000	3462	G	24.595637	84.949308	Normal
10/12/20	14:16:0	76	0.1	260	10.1	2600	3069	G	24.5958	84.950202	Normal
10/12/20	14:16:0	76	0.1	300	10.1	2300	2773	G	24.595925	84.95116	Normal
10/12/20	14:17:0	76	0.1	320	10.1	1900	2380	G	24.596447	84.95182	Normal
10/12/20	14:17:0	76	0.1	290	10.1	2900	3364	G	24.59632	84.95281	Normal
10/12/20	14:18:0	76	0.1	210	10.1	2100	2577	G	24.596105	84.953703	Normal
10/12/20	14:18:0	76	0.1	240	10.1	2400	2872	G	24.595843	84.954713	Normal
10/12/20	14:18:0	76	0.1	230	10.1	2300	2773	G	24.596005	84.955655	Normal
10/12/20	14:19:0	76	0.1	190	10.1	1900	2380	G	24.596702	84.956328	Normal
10/12/20	14:19:0	76	0.1	260	10.1	2600	3069	G	24.597545	84.956615	Normal
10/12/20	14:20:0	76	0.1	340	10.1	3400	3856	G	24.597782	84.957288	Curve
10/12/20	14:20:0	76	0.1	260	10.1	2600	3069	G	24.598255	84.958097	Normal
10/12/20	14:21:0	76	0.1	260	10.1	2600	3069	G	24.598758	84.958787	Normal
10/12/20	14:21:0	76	0.1	320	10.1	3200	3659	G	24.59895	84.95968	Normal
AVERAGE							3038				

Chd
11/12/20
J.E.

Salad
11.12.20
K.E.

25
15/12/20

सहायक अभियंता का कार्यालय

ग्रामीण कार्य विभाग, कार्य अवर प्रमंडल, डोंगी


पत्रांक..... AE/RWD/Dobhi/8PL

दिनांक..... 11/12/20

जाँच प्रतिवेदन


प्रखण्ड का नाम	योजना का नाम	पथ की लम्बाई	S.D.B.C परत की मोटाई	बिटुमिन CONTENT की मात्रा	BUMP INTEGRATOR का READING	अभियुक्ति
डोंगी	करमौनी पीडासीव रोड से निशुनपुर	1.600 Km.	25MM	5%	ATTACHED	SATISFACTORY


11/12/20
J.E


11/12/20
सहायक अभियंता,
ग्रामीण कार्य विभाग,
कार्य अवर प्रमंडल ... डोंगी

File : C:\Users\DELL\Desktop\Bump\26121753.Xls Section No. : 66, Eqn : test

Name of Customer : M/S MAA KOMLI CONST. Name of Work/ Road : GAYA JILA ANTARGAT DOBHI PRAKHAND KE



Call for
28.12.20
AT | Double

CONT. NAME-M/S MAA KOMLI CONST.

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
26/12/20	17:23:0	66	0.1	330	0	3300	3757	G	24.539653	84.887208	Normal
26/12/20	17:24:0	66	0.1	260	10.1	2600	3069	G	24.538775	84.887215	Speed Breaker
26/12/20	17:25:0	66	0.1	300	10.1	3000	3462	G	24.537872	84.887359	Normal
26/12/20	17:26:0	66	0.1	320	10.1	3200	3659	G	24.537011	84.88759	Normal
26/12/20	17:27:0	66	0.1	310	10.1	3100	3561	G	24.536068	84.898966	Normal
26/12/20	17:27:0	66	0.1	270	10.1	2700	3167	G	24.535254	84.887979	Normal
26/12/20	17:27:0	66	0.1	320	10.1	3200	3659	G	24.53441	84.888124	Normal
26/12/20	17:28:0	66	0.1	280	10.1	2800	3265	G	24.53298	84.888248	Normal
26/12/20	17:29:0	66	0.1	270	10.1	2700	3167	G	24.532105	84.887912	Normal
26/12/20	17:29:0	66	0.1	260	10.1	2600	3069	G	24.531337	84.887357	Normal
26/12/20	17:30:0	66	0.1	270	10.1	2700	3167	G	24.531747	84.886463	Normal
26/12/20	17:31:0	66	0.1	330	0	3300	3757	G	24.53222	84.885908	Speed Breaker
26/12/20	17:31:0	66	0.1	260	10.1	2600	3069	G	24.53278	84.885403	Normal
26/12/20	17:32:0	66	0.1	300	10.1	3000	3462	G	24.532918	84.884427	Normal
26/12/20	17:32:0	66	0.1	320	10.1	3200	3659	G	24.53327	84.883585	Normal
26/12/20	17:33:0	66	0.1	310	10.1	3100	3561	G	24.533397	84.882625	Normal
26/12/20	17:33:0	66	0.1	270	10.1	2700	3167	G	24.5335	84.882	Normal
26/12/20	17:34:0	66	0.1	320	10.1	3200	3659	G	24.533452	84.880638	Normal
26/12/20	17:34:0	66	0.1	320	10.1	3200	3659	G	24.533227	84.879713	Speed Breaker
26/12/20	17:35:0	66	0.1	280	10.1	2800	3265	G	24.533158	84.878855	Normal
26/12/20	17:36:0	66	0.1	270	10.1	2700	3167	G	24.533488	84.878315	Normal
26/12/20	17:36:0	66	0.1	260	10.1	2600	3069	G	24.53431	84.878097	Normal
26/12/20	17:36:0	66	0.1	270	10.1	2700	3167	G	24.535178	84.87845	Normal
26/12/20	17:37:0	66	0.1	330	0	3300	3757	G	24.536032	84.878938	Normal
26/12/20	17:37:0	66	0.1	260	10.1	2600	3069	G	24.536742	84.87941	Normal

Scanned by CamScanner

26/ 12/ 20	17: 38: 0	66	0.1	300	10.1	3000	3462	G	24.537562	84.87978	Normal
26/ 12/ 20	17: 39: 0	66	0.1	320	10.1	3200	3659	G	24.538337	84.880235	Normal
26/ 12/ 20	17: 39: 0	66	0.1	310	10.1	3100	3561	G	24.539197	84.880638	Normal
26/ 12/ 20	17: 39: 0	66	0.1	270	10.1	2700	3167	G	24.540027	84.880992	Normal
26/ 12/ 20	17: 40: 0	66	0.1	320	10.1	3200	3659	G	24.540763	84.88138	Normal
26/ 12/ 20	17: 40: 0	66	0.1	270	10.1	2700	3167	G	24.540027	84.880992	Normal
26/ 12/ 20	17: 41: 0	66	0.1	260	10.1	2600	3069	G	24.540763	84.88138	Normal
AVERAGE							3370				

*Sold in 2020
28.12.2020*

सहायक अभियंता का कार्यालय

ग्रामीण कार्य विभाग, कार्य अवर प्रमंडल ,..... 3/11

पत्रांक..... AE/RW/DOshi/Spl

दिनांक..... 28.12.2020

जाँच प्रतिवेदन

प्रखण्ड का नाम	योजना का नाम	पथ की लम्बाई	S.D.B.C परत की मोटाई	बिटुमिन CONTENT की मात्रा	BUMP INTEGRATOR का READING	अभियुक्ति
DOSHI	Gaya jila Andargu doshi prkhakke G.T Road piparghat pokhar se Hungarh waran prkhakke toha hokar	3.2	25 MM	5%	ATTACHED	SATISFACTORY

Chakla mahadali
toha tak Sadak
Nirman


28.12.20

सहायक अभियंता,

ग्रामीण कार्य विभाग

कार्य अवर प्रमंडल ... 3/11

File: C:\Users\DELL\Desktop\Bump\26121763.Nla. Section No. 67, Egm 1691
 Name of Customer: M/S MAA KOMI CONST., Name of Work/Road: G.T ROAD TO BEEZA, Lot/Job number:



Field
28.12.20
A.E. | B. B. B.

ROAD NAME- G.T ROAD TO BEEZA

CONT. NAME-M/S MAA KOMLI CONST.

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI CATEGORY ROAD	Latitude	Longitude	Event
26/12/20	17:47:0	67	0.1	270	0	2700	3167 G	24.541976	84.881498	Normal
26/12/20	17:48:0	67	0.1	280	10.1	2800	3265 G	24.542858	84.881807	Normal
26/12/20	17:48:0	67	0.1	250	10.1	2500	2970 G	24.543705	84.882013	Normal
26/12/20	17:48:0	67	0.1	290	10.1	2900	3364 G	24.544626	84.88226	Normal
26/12/20	17:49:0	67	0.1	190	10.1	1900	2380 G	24.545442	84.882386	Normal
26/12/20	17:49:0	67	0.1	210	10.1	2100	2577 G	24.546322	84.882371	Speed Breaker
26/12/20	17:50:0	67	0.1	200	10.1	2000	2478 G	24.547167	84.88262	Normal
26/12/20	17:50:0	67	0.1	210	10.1	2100	2577 G	24.548019	84.882565	Normal
26/12/20	17:51:0	67	0.1	260	10.1	2600	3069 G	24.548929	84.882557	Normal
26/12/20	17:51:0	67	0.1	250	10.1	2500	2970 G	24.549728	84.882621	Normal
26/12/20	17:52:0	67	0.1	290	10.1	2900	3364 G	24.550613	84.882437	Normal
26/12/20	17:53:0	67	0.1	190	10.1	1900	2380 G	24.55094	84.882271	Normal
26/12/20	17:54:0	67	0.1	210	10.1	2100	2577 G	24.545127	84.871288	Normal
26/12/20	17:54:0	67	0.1	200	10.1	2000	2478 G	24.551213	84.881579	Normal
26/12/20	17:55:0	67	0.1	280	10.1	2800	3265 G	24.551119	84.882290	Normal
26/12/20	17:55:0	67	0.1	290	10.1	2900	3364 G	24.551417	84.882354	Normal
26/12/20	17:56:0	67	0.1	260	0	2600	3069 G	24.551620	84.882152	Normal
26/12/20	17:56:0	67	0.1	210	10.1	2100	2577 G	24.551705	84.882031	Normal
26/12/20	17:57:0	67	0.1	200	10.1	2000	2478 G	24.551863	84.881901	Normal
26/12/20	17:57:0	67	0.1	280	10.1	2800	3265 G	24.552033	84.881763	Normal
26/12/20	17:58:0	67	0.1	290	10.1	2900	3364 G	24.552235	84.881698	Normal
26/12/20	17:58:0	67	0.1	260	0	2600	3069 G	24.552387	84.881546	Normal
AVERAGE							2912			

28.12.20
 28.12.20
 28.12.20

सहायक अभियंता का कार्यालय

ग्रामीण कार्य विभाग, कार्य अवर प्रमंडल , 3/2/21

पत्रांक..... AE/RWD/Doohi/SPL

दिनांक..... 28.12.2020

जाँच प्रतिवेदन

प्रखण्ड का नाम	योजना का नाम	पथ की लम्बाई	S.D.B.C परत की मोटाई	बिटुमिन CONTENT की मात्रा	BUMP INTEGRATOR का READING	अभियुक्ति
DOOHI	4-T Road to Beeza	2.2	25 MM	5%	ATTACHED	SATISFACTORY

28.12.20
सहायक अभियंता,
ग्रामीण कार्य विभाग ,
कार्य अवर प्रमंडल ... 3/2/21