FIELD INSPECTION REPORT

Date of Inspection:	2-01-2021	District: BANKA
Division: RWD. 6	CANKA-2	Length (km): 0.784 Km
Name of the Road: B	amdeo jetko	a Path to Dharmaichak (MMG)
Scheme/Programme:	MAINTENANCE	, 5Th year matulenance
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

SL No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality		
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	/
Unsatisfactory (U)	,

(Signature)

NAME: _ Rajundre Vadee

DESIGNATION: _ 12.1.2021

5. E