

FIELD INSPECTION REPORT

Date of Inspection :	District:	BUXAR
Division :	Length (km):	1.10
Name of the Road:	L064 - TOS TO DIHRI	
Scheme/Programme:	MAINTENANCE ✓	
Package No.:	BR08R 238	Road Id No.:
Status of the Project:	Ongoing Completed Under Maintenance ✓	
Work is a case of:	New Connectivity Up gradation/ Maintenance ✓	

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Home pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings slab approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m zones Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(S)

[Signature]

(Signature)

NAME:

FIELD INSPECTION REPORT

Date of Inspection :	District:	BUXAR
Division :	Length (km):	2.250
Name of the Road:	L065 Kathiya Bridge To Paniyari	
Scheme/Programme:	MAINTENANCE ✓	
Package No.: BR08R 195	Road Id No.:	
Status of the Project:	Ongoing Completed Under Maintenance ✓	
Work is a case of:	New Connectivity Up gradation Maintenance ✓	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S U
b)	Condition of Surfacing	✓ S U
c)	Riding Quality	✓ S U
d)	Road Camber	✓ S U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its plating	S SRI U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI



(Signature)

NAME: