

FIELD INSPECTION REPORT

Date of Inspection :	18/01/2021	District:	BUXAR
Division :	DUMRAON	Length (km):	2.00 km
Name of the Road:	DAFADEHRI TO HAROJA		
Scheme/Programme:	MAINTENANCE ✓		
Package No.:	BR08R	Road Id No.:	
Status of the Project:	Ongoing Completed Under Maintenance ✓		
Work is a case of:	New Connectivity Up gradation/ Maintenance ✓		

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ SU
b)	Condition of Surfacing	✓ SU
c)	Riding Quality	✓ SU
d)	Road Camber	✓ SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI N/A
c)	Condition of railings slab approach for Bridges	S/SRI N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

'S'

[Signature]
18/01/2021
AE

(Signature)

NAME: