

**FIELD INSPECTION REPORT**

Date of Inspection :	10.01.2024	District:	Buxar
Division :	Dumraon.	Length (km):	1.247 KM
Name of the Road:	Chhatanwar PMGSY road to Udiyangan		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U S
b)	Condition of Surfacing	✓ S/U S
c)	Riding Quality	✓ S/U S
d)	Road Camber	✓ S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No yes
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No yes
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓ Yes/No No Maintain
4.	Compliance History	
a)	Status of ATR's & any others	NA.

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

NAME:

10/01/2024

J.E

Dumraon

A.E

Dumraon

(Signature)