FIELD INSPECTION REPORT

Date of Inspection: DAJOH 2029 Division: Dana Palace		and the same of th	District: Patria .	
AND AND THE PARTY OF THE PARTY		and the second section of the second section s	Length (km): 1.50 ora	
	of the Road: NH		aruman Mandir	to Chama
	te/Programme:	MAINTENANCE		anne ann a chairm an dhaigh a dhaigh ag airm an dhair ann ag ann ann ag air aig air aig a' riad tainne, a gci
	ge No.:		oad Id No.:	
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance under Mainten		
	No. of the case of	New Connectivity/Up g	radation/ Maintenance	Water Co. (1) 10 10 10 10 10 10 10 10 10 10 10 10 10
Sl. No	1.	Parameters to be	checked	Remarks
1:	Pavement			
a)	Road Junction condition			S/U_
b)	Condition of Surfacing			S/U_
c)	c) Riding Quality			S/U-
d)	Road Camber			S/U_
e)	Whether free from defects such as visible cracks, expose aggregates in case of CC Pavement.		visible cracks, exposed	Vestito
<u>f)</u>	f) Contraction Joints provided or not		ivement)	Yes/No
g) Compaction of tlank/slope & r		lank/slope & raincuts if a	ny	Yes/No
2.	Cross Drainage			
<u>a)</u>	Condition of hea	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		SISKILL	
c)	Condition of raili	ngs/slab/approach for Br	idges	SISRINU
3.	Road Furniture			· · · · · · · · · · · · · · · · · · ·
\int_{S}^{s}	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			¥es/No
C	ompliance History			
S	tatus of ATR's &	any others		the state of

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	40.
Unsatisfactory (U)	5K/
A SECTION OF THE PROPERTY OF T	and the second

NAME: OF

DESIGNATION:

8/1/21

(Signature)

A.E. Manes

SOMARU RAMO