

Situation of work-

Agency by which work is executed-

Date of Measurement-

No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
FLOOD DAMAGED REPORT (FDR)					
Name of work:- Repair of Road					
Semaria to Gopalganj border					
via galimapur, Sikwara					
under FDR					
Agency:- Departmental					
Date of entry :- 16/01/2021					
Measurement					
Item No. ① construction of					
embankment with material					
obtained from borrow pit ---					
--- technical specification					
clause 301.5.					
At breach :-					
$8.00 \times 5.75 \times 1.50 = 69.00 \text{ m}^3$					
$4.00 \times 2.90 \times 1.20 = 13.92 \text{ m}^3$					
82.92 m ³					
Item No. ② Providing brick					
bats including spreading, laying					
--- direction of E/S including					

Continuation

[illegible]

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of cost</u>					
All qty vide T.M.B.					
Item No. (1) Construction of embankment with material obtained from borrow pits---					
P/1 item No. 1/1					
82.92 m ³ @ RS 190.57/m ³					RS 15802.00
Item No. (2) Providing brick bats including spreading ---					
P/2 item No. 2/2					
19.26 m ³ @ RS 2412.11/m ³					RS 46457.00
Item No. (3) Providing and laying RCC Pipe NP3 - - -					
P/2 item No. 3/3					
2.50 M @ RS 2733.55/M					RS 6833.00
					RS 69092.00
Labour cess 1%					RS 690.00
GST 12%					RS 8291.00

Continuation