

1

Situation of Work-

Agency by which work is executed-

Date of Measurement-

No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work.

[illegible]

ABSTRACT OF COST

Sch. XLV-Form No.134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Providing and laying dry graded brick bats - etc. vide TMB Page 1 35.44 m ³ @ Re 2116 = 22 P ⁰⁰ Re 74993 = 55 Say Re 74993 = 55					
<div style="display: flex; justify-content: space-between;"> <div> <p><i>Handwritten:</i> 5/1/21 JE/Chavara</p> </div> <div> <p><i>Handwritten:</i> 05/11/21 A G</p> </div> <div> <p><i>Handwritten:</i> 21/1/2021</p> </div> </div>					
<div style="text-align: right;"> <p>कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमण्डल, रक्सौल</p> </div>					

कार्यपालक अभियंता का कार्यलय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, मोतिहारी।

पत्रांक2769(अनु०)

मोतिहारी / दिनांक 28-12-2020

प्रेषक :- कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, मोतिहारी।

सेवा में,
अधीक्षण अभियंता,
ग्रामीण कार्य विभाग,
कार्य अंचल, मोतिहारी।

विषय :- कार्य प्रमंडल रक्सौल अन्तर्गत वर्ष-2020 में बाढ़ एवं अतिवृष्टि के कारण क्षतिग्रस्त पथों को मोटेरेबुल करने हेतु किए गए कार्यों की जाँच के संबंध में।

प्रसंग:- मु०अ०-04 (मु०) विविध (कार्य)-23-40/216-2789 पटना, दिनांक-21.08.2020 एवं भवदीय कार्यालय आदेश ज्ञापांक-1344 दिनांक-28.08.2020


महोदय,


उपर्युक्त विषयक प्रसांगिक पत्र के अनुपालन में कार्य प्रमंडल, रक्सौल द्वारा उपलब्ध कराये गये मोटेरेबुल पथों की सूची में अंकित पथों का अधोहस्ताक्षरी के द्वारा निरीक्षण किया गया निरीक्षण के दौरान कार्य प्रमंडल, रक्सौल द्वारा प्रतिवेदित सभी पथों में मोटेरेबुल का कार्य कराया गया है एवं वर्तमान यातायात चालू है।

सादर सूचनार्थ एवं अग्रेत्तर कार्यवाई हेतु समर्पित।

अनु:- निरीक्षण किए गए पथों की सूची।

विश्वासभाजन,


28/12/20
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, मोतिहारी।


28/12/20
र.ए.

List of Road Damaged due to Flood 2020-21

Sr. No.	Sl. No.	Road Name	System	Road Status	Is Maintenance (Y/N)	Is Agreement (Y/N)	Length (Kms.)	Length of Damage Part Due to Flood (in M)	Actual Restoration Amount (in Lac)	Remarks	Start Latitude	Start Longitude	End Latitude	End Longitude	Block
1	Raxaul	PWD Road at Matter Chowk - Ekdari (BR-11R-299)	PMGSY	On Going	No	No	2.46	20	0.75	Badly Damaged	26.815448	85.008412	26.845772	85.008412	Chhauradano
2	Raxaul	Jaisachowk Chhauradano to Bahadurpur	MMGSY-NDG(BRICS)-1	On Going	No	No	1	200	6.26	Badly Damaged	26.85194	84.999995	26.85354	84.999995	Chhauradano
3	Raxaul	Bahadurpur - Balshakhawa (BR-11R-014)	PMGSY	On Going	No	No	3.25	80	14.24	Breach	26.846253	84.934377	26.850553	84.934377	Chhauradano
4	Raxaul	Tatariya Tinkoni Toia to REO Road Jitpur to Dubha PMGSY	MMGSY[SC]	On Going	No	Yes	1.905	40	1.9	Breach & Badly Damaged	26.851687	84.947548	26.852103	84.947548	Chhauradano
5	Raxaul	REO Road Jitpur - Dubha Bazar (BR-11-12B)	PMGSY	On Going	No	Yes	2.3	130	15.28	Breach	26.850368	84.943817	26.851225	84.943817	Chhauradano
6	Raxaul	P.W.D Path Narayan Chowk to Pakariya Ghat	MMGSY-NDG(BRICS)-1	On Going	No	Yes	6.5	60	1.61	Breach	26.776777	84.97868	26.793453	84.97868	Chhauradano
7	Raxaul	Rampur PMGSY Road To Pakariya Toia	MMGSY[Gen]	Completed	Yes	Yes	1.708	30	6.29	Breach	26.804328	84.915982	26.799817	84.915982	Chhauradano
8	Raxaul	Juafer to Malahi (BR-11R-545)	PMGSY	Completed	Yes	Yes	3.575	45	4.34	Breach	26.792087	85.004925	26.772769	84.999222	Chhauradano
9	Raxaul	Sukhalahiya Paschim Toia Reo Road Jitpur to Dubha	MMGSY[SC]	On Going	No	Yes	1.52	25	1.14	Badly Damaged	26.829587	84.95785	26.831581	84.95819	Chhauradano
10	Raxaul	REO Road at Semrahiya - Mathiya Brit (BR-11R-016)	PMGSY	Completed	No	No	3.63	15	3.65	Breach	26.802568	84.954703	26.803253	84.954709	Chhauradano
11	Raxaul	Kadarn Chowk Lakhaura to Naurangiya	MMGSY[Gen]	On Going	No	Yes	1.2	55	3.9	Breach	26.77167	84.958782	26.770183	84.954902	Chhauradano
12	Raxaul	Shekh Toll to Pakariya PMGSY Road	MMGSY[SC]	On Going	No	Yes	0.81	15	0.68	Breach	26.77773	84.967244	26.781502	84.96489	Chhauradano
13	Raxaul	L035-REO ROAD AT HRMANI - BANJARI (BR-11R-387)	PMGSY	Completed	No	No	3.481	185	5.98	Badly Damaged	26.792871	84.537812	26.771947	84.922766	Chhauradano

28/12/20
E.E. (R.O.D.)
report karne