

Inspection Report for Flood Damage Work

Date

- 1 Name of PIUs- Gyan Vithalpur
- 2 Name of Block/Road- minapur / wasul Nath House to Handikpur Jha House


A For Road

- 1 Damage Location/Chainage 0.520 km, 0.580 km, 0.590 km
- 2 Damage Length 0.022 km
- 3 Nature of Damage
- 4 Details of Restoration Works-
 - i Material being used in Restoration Works- Brick balls
 - ii Equipments/Tools being used in Restoration Works- Tractor
 - iii Procedure Taken up in Restoration Works-
 - iv Restored Length 0.022 km

B. For Bridge

- 1 Damage Location/Chainage
- 2 Damage Length
- 3 Nature of Damage
- 4 Details of Restoration Works-
 - i Material being used in Restoration Works-
 - ii Equipments/Tools being used in Restoration Works-
 - iii Procedure Taken up in Restoration Works-
 - iv Restored Length

Signature of JE/ AE/ EE


Signature
(Name of Inspector)

EE

RWD muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Wasuki Nath House to Nandkishor Jha House

District Muzaffarpur

Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km) 0.746 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	1.728
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	1.728
TOTAL COST OF PROJECT IN LACS =		1.728

Ramesh
11/1/21

JE
RWD

A. S.
11/01/21

AE
RWD

N. P.
11/01

EE
RWD

Technically approved for Rs 1.728 lac
(Rupees one lac seventy two thousand eight hundred only)

U. M.
13.1.21
SE

RWD work circle
muzaffarpur