

(FDR-2020)
N/W - Temporary Restoration of Road from Dantwad
Dhanordihuli to Unchidih

Schedule XLV Form No. 134.

Rasau. DIVISION

Dangarwa SUB-DIVISION

Measurement Book

728

Continuation

Sch. XLV-Form No. 134

Sch. XLV-Form No. 154					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
Abstract of Cost.					
Earth Filling in Road Breaches etc.					
TMB Pg. No. 1(1) - 577.69 m ³					
@ R 382.42/- = R 220920=00					
P/L of Bridge Bats including dyke rammy etc.					
TMB Pg. No. 1(2) - 114.875 m ³					
@ R 2085.03/- = R 239518=00					
Total = R 460438=00					

Signature
2/8/20
J.E.

Signature
5/1/21
J.E.

Signature
AE 5/1/2021
Rangashw

Signature
5/1/2021

Executive Engineer
Rural Works Department
Works Division, Raxaul

कार्यपालक अभियंता का कार्यलय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, मोतिहारी।

पत्रांक 2769 (अनु०)

मोतिहारी / दिनांक 28-12-2020

प्रेषक :- कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, मोतिहारी।

सेवा में,
अधीक्षण अभियंता,
ग्रामीण कार्य विभाग,
कार्य अंचल, मोतिहारी।

विषय :- कार्य प्रमंडल रकसौल अन्तर्गत वर्ष-2020 में बाढ़ एवं अतिवृष्टि के कारण क्षतिग्रस्त पथों को मोटेरेबुल करने हेतु दिए गए कार्यों की जाँच के संबंध में।

प्रसंग :- मु०अ०-04 (मु०) विवेद (कार्य)-23-40/216-2789 पटना, दिनांक-21.08.2020 एवं भवदीय कार्यालय आदेश ज्ञापक-1344 दिनांक-28.08.2020


महोदय,

उपर्युक्त विषयक प्रसांगिक पत्र के अनुपालन में कार्य प्रमंडल, रकसौल द्वारा उपलब्ध कराये गये मोटेरेबुल पथों की सूची में अंकित पथों का अधोहस्ताक्षरी के द्वारा निरीक्षण किया गया निरीक्षण के दौरान कार्य प्रमंडल, रकसौल द्वारा प्रतिवेदित सभी पथों में मोटेरेबुल का कार्य कराया गया है एवं वर्तमान यातायात चालू है।

सादर सूचनार्थ एवं अग्रेत्तर कार्रवाई हेतु समर्पित।

अनु:- निरीक्षण किए गए पथों की सूची।

विश्वासभाजन,


28/12/20
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, मोतिहारी।

28/12/20
V.E.

List of Road Damaged due to Flood 2020-21

SINO	Division	Road Name	Scheme	Road Status	Is Maintenance (Y/N)	Is Agreement (Y/N)	Length (In Km.)	Length of Damage Part Due to Flood in M	Actual Restoration Amount (In Lac)	Remarks	Start Latitude	Start Longitude	End Latitude	End Longitude	Block
1	Raxaul	T01 NH-28A Ramgarhwa to Pakhnahiya Part of Length 9.20 Km of Ramgarhwa-Balthar via Sikata Road	MR	Completed	Yes	Yes	5.2	519	13.79	Badly Damaged	26.877707	84.782244	26.877366	84.782244	Ramgarhwa
2	Raxaul	Ramgarhwa - Sukhismra (BR-11R-033)	PMGSY	Completed	No	No	5.6	120	15.52	Breach Near Pond	26.884082	84.767253	26.883939	84.767253	Ramgarhwa
3	Raxaul	Mishrauliya Lohapuri to Vani Mishrauliya	MMGSY[Gen]	On Going	No	Yes	1.48	40	3.91	Breach near culvert.	26.856772	84.808345	26.795765	84.808345	Ramgarhwa
5	Raxaul	NH-28A to Meena Tola (Part of Length 5.38 Km of NH28A to Laxmipur Road	MR	Completed	Yes	Yes	3.8	107	3.03	Breach	26.877051	84.810369	26.874434	84.810369	Ramgarhwa
6	Raxaul	NH-28A Road Semaar Chowk to Gandhi Gram Kushta Colony	MMGSY[SC]	Completed	Yes	Yes	1.13	75	2.86	Breach & Badly Damaged	26.860702	84.779436	26.860802	84.779436	Ramgarhwa
7	Raxaul	NH-28 to Kharkatwa	PMGSY	On Going	No	Yes	3	301	8.78	Badly Damaged Near Pond	26.905561	84.7976	26.913631	84.800462	Ramgarhwa
8	Raxaul	NH-28A Path Chilhapti To San Tola Katkenwa	MMGSY[Gen]	Completed	Yes	Yes	2.3	179	7.15	Breach & Badly Damaged	26.813264	84.74192	26.80623	84.751044	Ramgarhwa
9	Raxaul	NH-28A Road Muria To Sishbaniya Pokhra	MMGSY[SC]	Completed	Yes	Yes	4.573	92	2.88	Breach & Badly Damaged	26.813209	84.789441	26.869867	84.781651	Ramgarhwa
10	Raxaul	L041-Purushottampur to Balua	PMGSY	Completed	Yes	Yes	3	105	4.23	Breach & Badly Damaged	26.884941	84.837248	26.885191	84.838505	Ramgarhwa
11	Raxaul	Danhardiuli - unchidih (BR-11R-042)	PMGSY	Completed	No	No	2.188	70	4.78	Breach & Badly Damaged	26.924685	84.807302	26.920371	84.814624	Ramgarhwa
12	Raxaul	Pakhnahiya Konarawa to Kalikapur	MMGSY[Gen]	Completed	Yes	Yes	2.506	65	1.78	Badly Damaged	26.893126	84.77557	26.93135	84.782481	Ramgarhwa
13	Raxaul	T04 House of Umeshwar Singh to Baudha Harijan Basti	MMGSY[SC]	Completed	Yes	Yes	1.17	118	3.24	Badly Damaged	26.897403	84.803945	26.89787	84.802588	Ramgarhwa
14	Raxaul	Ramgarhwa - Singasni (BR-11R-281)	PMGSY	On Going	No	No	6.032	105	2.7	Badly Damaged	26.869356	84.777737	26.87081	84.774889	Ramgarhwa
15	Raxaul	Pakhnahia - Khonarwa (BR-11R-041)	PMGSY	On Going	No	Yes	3.819	83	1.88	Badly Damaged	26.932071	84.777019	26.919618	84.774768	Ramgarhwa
16	Raxaul	L038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	Yes	Yes	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
17	Raxaul	Pakhnahia - Garhwa (BR-11R-040)	PMGSY	Completed	No	No	7.082	53.5	1.25	Badly Damaged	26.913007	84.763809	26.89494	84.733856	Ramgarhwa
18	Raxaul	NH-28 A to Laxmipur Road.	MMGSY OLD	Completed	No	No	5.38	37	1.25	Badly Damaged	26.86617	84.823224	26.866173	84.823278	Ramgarhwa
19	Raxaul	L034-L027 Triveni to Bherihari (VR34)	PMGSY	Completed	Yes	Yes	4.732	67	1.8	Causeway Badly Damaged	26.849351	84.742007	26.948346	84.741633	Ramgarhwa

28/12/21
E.E. (R.D.D.)
Mofidex