

Name of Work-

1

Situation of Work-

Agency by which work is executed-

Date of Measurement-

No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work.)

| Particulars | Details of actual measurement | | | | Contents of area |
|--|-------------------------------|----|----|----|------------------|
| | No. | L. | B. | D. | |
| CH- 2245 (FDR) 2020 | | | | | |
| Name of work:- Temporary | | | | | |
| Restoration of Road Laxminagar to Laxminagar | | | | | |
| Agency- Departmental | | | | | |
| Authority- E. E Road Raxaul | | | | | |
| Date of Entry- 20/8/20 | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

① Providing bedding

Bricks bats

at ch- 800 M

$$20 \text{ m} \times \left(\frac{3.50 + 4.50}{2} \right) \text{ m} \times \left(\frac{0.50 + 0.75}{2} \right) \text{ m}$$

$$= 50.0 \text{ m}^3$$

20/8/20
JE/Rev

20/8/20
AE

2

[illegible]

कार्यपालक अभियंता का कार्यलय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, मोतिहारी।

पत्रांक2769(अनु०)

मोतिहारी / दिनांक 28-12-2020

प्रेषक :- कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, मोतिहारी।

सेवा में,
अधीक्षण अभियंता,
ग्रामीण कार्य विभाग,
कार्य अंचल, मोतिहारी।

विषय :- कार्य प्रमंडल रक्सौल अन्तर्गत वर्ष-2020 में बाढ़ एवं अतिवृष्टि के कारण क्षतिग्रस्त पथों को मोटेरेबुल करने हेतु किए गए कार्यों की जाँच के संबंध में।

प्रसंग:- मु०अ०-04 (मु०) विविद (कार्य)-23-40/216-2789 पटना, दिनांक-21.08.2020 एवं भवदीय कार्यालय आदेश ज्ञापक--1344 दिनांक-28.08.2020


महोदय,

उपर्युक्त विषयक प्रसांगिक पत्र के अनुपालन में कार्य प्रमंडल, रक्सौल द्वारा उपलब्ध कराये गये मोटेरेबुल पथों की सूची में अंकित पथों का अधोहस्ताक्षरी के द्वारा निरीक्षण किया गया निरीक्षण के दौरान कार्य प्रमंडल, रक्सौल द्वारा प्रतिवेदित सभी पथों में मोटेरेबुल का कार्य कराया गया है एवं वर्तमान यातायात चालू है।


सादर सूचनार्थ एवं अग्रेत्तर कार्रवाई हेतु समर्पित।

अनु:- निरीक्षण किए गए पथों की सूची।

विश्वासभाजन,

 28/12/20

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, मोतिहारी।

 28/12/20
S.E.

List of Road Damaged due to Flood 2020-21

| S.No | Division | Road Name | Scheme | Road Status | Is Maintenance (Y/N) | Is Agreement (Y/N) | Length (Km.) | Length of Damage Part Due to Flood (In M) | Actual Restoration Amount (In Lac) | Remarks | Start Latitude | Start Longitude | End Latitude | End Longitude | Block |
|------|----------|---|------------|-------------|----------------------|--------------------|--------------|---|------------------------------------|------------------------|----------------|-----------------|--------------|---------------|--------|
| 20 | Raxaul | Hawal Adda Siman Tola Road to Dhupwa Tola via S.S.B CampBhatuwaha (Part -2) | MR | Completed | Yes | Yes | 3.600 | 130 | 3.18 | Breach & Badly Damaged | 27.01069 | 84.813528 | 27.001268 | 84.822645 | Raxaul |
| 21 | Raxaul | Bhelahi - Noniya to Baudhimai | BAOP | Completed | No | No | 0.870 | 50 | 2.01 | Breach | 26.992043 | 84.840403 | 26.998167 | 84.843543 | Raxaul |
| 22 | Raxaul | N.H.26 A - Sri Rampur (BR-11R-020) | PMGSY | On Going | No | Yes | 1.842 | 105 | 5.15 | Breach | 26.946917 | 84.870012 | 26.691724 | 84.690514 | Raxaul |
| 23 | Raxaul | Siswa to Gad Bahur | MR | On Going | No | Yes | 21.000 | 240 | 9.96 | Badly Damaged | 26.993289 | 84.793881 | 26.934712 | 84.757347 | Raxaul |
| 24 | Raxaul | Palanwa thana to Dhangar toll hote hue Bahura PMGSY Road tak in Raxaul Block | MR | Completed | No | No | 1.600 | 140 | 5.45 | Badly Damaged | 26.916666 | 84.765375 | 26.916128 | 84.765117 | Raxaul |
| 25 | Raxaul | GBC Canal to Mahadeva S.S.B Camp | BAOP | Completed | No | No | 2.080 | 35 | 3.11 | Badly Damaged | 26.975205 | 84.876156 | 26.97493 | 84.876257 | Raxaul |
| 26 | Raxaul | LO25 Palanwa to Harjan Tola | MMGSY[Gen] | On Going | No | Yes | 0.786 | 95 | 5.35 | Badly Damaged | 26.91785 | 84.770637 | 26.917913 | 84.768435 | Raxaul |
| 27 | Raxaul | LO24 Lachhmanwa to Ahir Tola | MMGSY[Gen] | Completed | Yes | Yes | 1.042 | 40 | 3.00 | Breach | 26.972033 | 84.803003 | 26.972342 | 84.802962 | Raxaul |
| 28 | Raxaul | Laxmipur - Laxminitya (BR-11R-034) | PMGSY | On Going | No | Yes | 1.949 | 20 | 1.00 | Badly Damaged | 26.969449 | 84.790083 | 26.968922 | 84.789899 | Raxaul |
| 29 | Raxaul | Bahura PMGSY Road to Bajrang Chowk tak in Raxaul Block | MR | On Going | No | No | 1.700 | 127 | 6.91 | Badly Damaged | 26.924208 | 84.755008 | 26.93211 | 84.746215 | Raxaul |
| 30 | Raxaul | Anand sagar to Gadiyari Tola | MMGSY[Gen] | On Going | No | Yes | 1.314 | 27 | 1.97 | Breach | 26.946879 | 84.712666 | 26.946999 | 84.712878 | Raxaul |
| 31 | Raxaul | T04 Tyagi Math to Baari Tola | MMGSY[Gen] | Completed | Yes | Yes | 1.800 | 42 | 2.33 | Badly Damaged | 26.953325 | 84.764327 | 26.955075 | 84.764295 | Raxaul |
| 32 | Raxaul | Repair of road from Harinahi to Pantoka | MR | Completed | Yes | Yes | 7.300 | 210 | 7.43 | Badly Damaged | 26.980996 | 84.826493 | 26.971599 | 84.821605 | Raxaul |
| 33 | Raxaul | T06-Bhelahi to Nonca Road 6.00 km to 12.00 km High level Bridge across Tilwe river in the Road from Bhelahi To nonca Road At Chaigne 0.00km | PMGSY | On Going | No | Yes | 330.90M | 125 | 6.12 | Diversions Washout | 27.004556 | 84.810108 | 27.004634 | 84.809932 | Raxaul |
| 34 | Raxaul | RCC Bridge at Harinahi to Pantoka at Ch 3.6km | PMGSY | On Going | No | Yes | 17.95M | 40 | 4.11 | Diversions Washout | 26.998709 | 84.84317 | 26.99037 | 84.84302 | Raxaul |

2028/12
E.E. (R.D.P.)
MORHAR