

(FDR-2020)

N/W-Temporary Restoration of Road from TOI NH-28A
Ramgarhwa to Pakhnahta Port of Length 9.20km

Schedule XLV Form No. 134.
of Ramgarhwa-Balthar via Sikta.

Raxaul. DIVISION

Ramgarhwa. SUB-DIVISION

Measurement Book

731

Name of work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

[illegible]

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					B.F = 536.95/m ³
4.80km	11m	2.80m	0.30		= 9.24m ³
5.0km	65m	4.05m	0.40		= 105.30m ³
					← Total = 651.491m ³
Chrom 21/8/20 J.E					AP 21/8/20 A/E Rangarajwz

Abstract of CV

① P/L of Brick Bats including
 Light ramming — etc.
 TMB Pg. No. 1(1) — 651.491m³
 @ Rs 2116.24 = Rs 1378698 = ∞

~~Chrom~~
 24/5/21
 J.E

~~AP~~
 5/11/2021
 A/E Rangarajwz

~~Chrom~~
 5/11/2021
 Executive Engineer
 Rural Works Department
 Works Division, Raxaul

Continuation

कार्यपालक अभियंता का कार्यलय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, मोतिहारी।

पत्रांक 2769 (अनु०)

मोतिहारी / दिनांक 28-12-2020

प्रेषक :- कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, मोतिहारी।

सेवा में,

अधीक्षण अभियंता,
ग्रामीण कार्य विभाग,
कार्य अंचल, मोतिहारी।

विषय :- कार्य प्रमंडल रक्सौल अन्तर्गत वर्ष-2020 में बाढ़ एवं अतिवृष्टि के कारण क्षतिग्रस्त पथों को मोटेरेबुल करने हेतु लिए गए कार्यों की जाँच के संबंध में।

प्रसंग :- मु०अ०-04 (मु०) विविद (कार्य)-23-40/216-2789 पटना, दिनांक-21.08.2020 एवं भवदीय कार्यालय आदेश ज्ञापक-1344 दिनांक-28.08.2020


महोदय,

उपर्युक्त विषयक प्रसांगिक पत्र के अनुपालन में कार्य प्रमंडल, रक्सौल द्वारा उपलब्ध कराए गये मोटेरेबुल पथों की सूची में अंकित पथों का अधोहस्ताक्षरी के द्वारा निरीक्षण किया गया निरीक्षण के दौरान कार्य प्रमंडल, रक्सौल द्वारा प्रतिवेदित सभी पथों में मोटेरेबुल का कार्य कराया गया है एवं वर्तमान यातायात चालू है।

सादर सूचनार्थ एवं अग्रेत्तर कार्रवाई हेतु समर्पित।

अनु:- निरीक्षण किए गए पथों की सूची।

विश्वासभाजन,


28/12/20
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, मोतिहारी।

28/12/20
र.ए.

List of Road Damaged due to flood 2020-21

SINo	Division	Road Name	Scheme	Road Status	Is Maintenance (Y/N)	Is Agreement (Y/N)	Length (In Km.)	Length of Damage Part Due to Flood in M	Actual Restoration Amount (In Lac)	Remarks	Start Latitude	Start Longitude	End Latitude	End Longitude	Block
1	Raxaul	T01 NH-28A Ramgarhwa to Pakhnahia Part of Length 9.20 Km of Ramgarhwa-Balthar via Sikata Road	MR	Completed	Yes	Yes	5.2	519	13.79	Badly Damaged	26.877707	84.782244	26.877966	84.782244	Ramgarhwa
2	Raxaul	Ramgarhwa - Sukhisenra (BR-11R-039)	PMGSY	Completed	No	No	5.6	120	15.52	Breach Near Pond	26.864082	84.767253	26.883999	84.767253	Ramgarhwa
3	Raxaul	Mishrauliya Lohapul to Vani Mishrauliya	MMGSY[Gen]	On Going	No	Yes	1.48	40	3.91	Breach near culvert.	26.856772	84.808345	26.795765	84.808345	Ramgarhwa
4	Raxaul	NH-28 Patni - Badriyahi Ghat	PMGSY-NEA	Completed	No	No	5	25	1.07	Breach	26.835413	84.82028	26.835196	84.82028	Ramgarhwa
5	Raxaul	NH-28A to Meena Tola (Part of Length 5.38 Km of NH28A to Laxmipur Road	MR	Completed	Yes	Yes	3.8	107	3.08	Breach	26.877061	84.810369	26.874434	84.810369	Ramgarhwa
6	Raxaul	NH-28A Road Semar Chowk to Gandhi Gram Kustha Colony	MMGSY[SC]	Completed	Yes	Yes	1.13	75	2.86	Breach & Badly Damaged	26.860702	84.779436	26.860802	84.779436	Ramgarhwa
7	Raxaul	NH-28 to Kharkatwa	PMGSY	On Going	No	Yes	3	301	8.78	Badly Damaged Near Pond	26.905561	84.7976	26.913631	84.800462	Ramgarhwa
8	Raxaul	NH-28A Path Chijhapti To Sah Tola Katkenwa	MMGSY[Gen]	Completed	Yes	Yes	2.3	179	7.15	Breach & Badly Damaged	26.813264	84.74192	26.80823	84.751044	Ramgarhwa
9	Raxaul	NH-28A Road Muria To Sishbaniya Pokhra	MMGSY[SC]	Completed	Yes	Yes	4.573	92	2.88	Breach & Badly Damaged	26.863209	84.789441	26.869867	84.781651	Ramgarhwa
10	Raxaul	L041-Purushottampur to Balua	PMGSY	Completed	Yes	Yes	3	105	4.23	Breach & Badly Damaged	26.884941	84.837248	26.885191	84.838505	Ramgarhwa
11	Raxaul	Danhardiuli - unchidih (BR-11R-042)	PMGSY	Completed	No	No	2.188	70	4.78	Breach & Badly Damaged	26.924685	84.807302	26.920371	84.814624	Ramgarhwa
12	Raxaul	Pakhnahia Konarawa to Kalikapur	MMGSY[Gen]	Completed	Yes	Yes	2.506	65	1.78	Badly Damaged	26.893126	84.77557	26.93135	84.782481	Ramgarhwa
13	Raxaul	T04 House of Umeshwar Singh to Baudha Harijan Basti	MMGSY[SC]	Completed	Yes	Yes	1.17	118	3.24	Badly Damaged	26.897403	84.803945	26.89787	84.802588	Ramgarhwa
14	Raxaul	Ramgarhwa - Singasni (BR-11R-281)	PMGSY	On Going	No	No	6.032	105	2.7	Badly Damaged	26.869356	84.777737	26.87081	84.774889	Ramgarhwa
15	Raxaul	Pakhnahia - Khonarwa (BR-11R-041)	PMGSY	On Going	No	Yes	3.819	83	1.88	Badly Damaged	26.932071	84.777019	26.919618	84.774768	Ramgarhwa
16	Raxaul	L038-NH-28 to Malahi Tola (BR-11R-420)	PMGSY	Completed	Yes	Yes	2	49	1.93	Breach & Badly Damaged	26.878601	84.804409	26.878449	84.804362	Ramgarhwa
17	Raxaul	Pakhnahia - Gerhwa (BR-11R-040)	PMGSY	Completed	No	No	7.082	53.5	1.25	Badly Damaged	26.913007	84.763809	26.89494	84.733856	Ramgarhwa
18	Raxaul	NH-28 A to Laxmipur Road.	MMGSY OLD	Completed	No	No	5.38	37	1.25	Badly Damaged	26.86617	84.823224	26.866173	84.823278	Ramgarhwa
19	Raxaul	L034-L027 Triveni to Bherihari (VR34)	PMGSY	Completed	Yes	Yes	4.732	67	1.8	Causeway Badly Damaged	26.849351	84.742007	26.948346	84.741633	Ramgarhwa

28/12/21
 E.E. (R.D.D.)
 M.O. Kharwa