

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibha/Car

2 Name of Block/Road :- katra/ katra Dhabia Urandhi to PWD to sonpur Ramram
mishra House side.

(A) For Road:

✓ 1. Damage Location/Chainage :- 1.350, 1.410 km

2. Damage Length :- 0.105 km

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:-

Brick balls & Local sand

(ii) Equipment's/Tools being used in Restoration works:-

Tractor

(iii) Procedure taken up in Restoration works:

(iv) Restored Length :- 0.105 km

(B) For Bridge:

X 1. Damage Location/Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE

RWD muzaffarpur East-1

GENERAL ABSTRACT

Name of Road	Katra Dhoobia Ghandhi to PWD to Sonpur Raman Mishra House Tak
District	Muzaffarpur
Block	Katra
Division	Muzaffarpur East-2
Length of Road (in Km)	2.910 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Jhama metal	21.274
3	Sand Filling	3.920
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	25.194
TOTAL COST OF PROJECT IN LACS =		25.194

Say Rs 25.194 lacs

11/12/21
JE
RWD

AE
RWD

EE
RWD

Technically approved for Rs 25.194 lakh
(Rupees Twenty five lakh nineteen thousand four hundred only)

SE

RWD work circle
muzaaffarpur