

Name of Work:-

Estimate for Repair of Road breaches (Damaged by Flood) for Motorability in Anand Sagar to Gadiyani Tola For year 2020.

Head - 2245

Length- 1.320KM

SI No.	Item No.	Name of Item	unit	No	Length	Width	Height	Qty.	Rate	Amount
1		Earth work in Excavation for roadwork in soil with hydraulic excavator of 0.9 cum bucket capacity including cutting Only and as per Technical Specification Clause 302.3	cum	As Per		Appendix I		0.000	412.47	0.00
2		Providing & Laying dry graded Brick Bats including light ramming etc. all complete as per approved design, specification and direction of E/L.	cum	As Per		Appendix II		94.50	2085.03	197035.34
3		Providing and laying reinforced cement concrete pipe NP3 for Cross Drainage 1000mm dia	RM	1Row x2Nos x2.50M=		5M		0.000	4032.75	0.00
TOTAL (in Rs.)										197035.34
Say Rs										197000.00

[Signature]
21/12/20

Junior Engineer,
Rural Works Department,
Works Section, Raxaul

[Signature]
21/12/20

Assistant Engineer,
Rural Works Department,
Works Sub Division, Raxaul

[Signature]
21/12/20

Executive Engineer,
Rural Works Department,
Works Division, Raxaul

Post Facto T.A./TS is accorded for Rs. 1,97,000 = 1
(.....crore.....One.....Ninety Seven.....lacs.....thous.....
.....hundred.....) only

[Signature]
25/12/20
S.E. (R.W.D.)
works Circle
Motihari

[Signature]
29.12.20