

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhalead

2 Name of Block/Road :- Katoa / PWD road Gargia Chowk to Basant Jangh road

(A) For Road:

- ✓
1. Damage Location/Chainage :- 0.200 km, 0.280 km, 0.375 km
 2. Damage Length :- 0.060 km
 3. Nature of Damage :-
 4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Bricks and local sand
 - (ii) Equipment's/Tools being used in Restoration works:- Tractor
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.060 km

(B) For Bridge:

- X
1. Damage Location/Chainage :-
 2. Damage Length :-
 3. Nature of Damage :-
 4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE

Signature

(Name of Inspection)

EE

RMD work Division muzzafarpur
Gaut - 1

GENERAL ABSTRACT

Name of Road PWD Road Gangia Chowk to to Basant Jane Wali Sarak

District Muzaffarpur

Block Katra

Division Muzaffarpur East-2


Length of Road (in Km) 1.801 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
		0.000
1	Earthwork	2.223
2	Jhama metal	2.767
3	Sand Filling	0.000
4	Sand bag	0.000
5	H.P.	4.991
	GRAND SUB TOTAL	4.991
TOTAL COST OF PROJECT IN LACS =		


say 4-99 lac


11/1/21

JE
RWD



11.1.2021

AE
RWD


11/1

EE
RWD

Technically approved for Rs 4-99 lac
(Rupees four lac ninety nine thousand only)


11/1/21
SE

RWD work circle
muzaffarpur