77

(4)

Inspection Report For Flood Damage Work

1)	-1	1	12	

1 Name of Pius: Corportani - 2

2 Name of Block/Road: Backunthput / Dharambari Puro Pata 70 Kazi Kuya, Ko

A For Road

1 Damage Location / Chainage: 300 m +0 485 m

2 Damage Length: 15-1 m

3 Nature of Damage: Heavy Ram / Flood

4 Details of Restroration Works:

i. Material being used in Restoration Works: But Bals

ii Equipments / Tools being used in Restoration Works: 900, Tractor, Trele, Belch, Shaw 1

iii Procedure taken up in Restoration Works. 444

iv Restored Length:

15/m

8 For Bridge

NIA

- 1 Damage Location / Chainage:
- 2 Damage Length:
- 3 Nature of Damage:
- 4 Details of Restroration Works:
 - Material being used in Restoration Works:
 - ii Equipments / Tools being used in Restoration Works:
 - iii Procedure taken up in Restoration Works:
 - iv Restored Length

量何5000

AE

C25/9/

Executivethedineer

(Na Rowi DosWo Ror)

Hathua



ग्रामीण कार्व विभाग

Rural Works Department, Govt. of Bihar

FLOOD DAMAGED REPAIR (F.D.R.)

STATE :- BIHAR

DISTRICT :- GOPALGANJ

BLOCK :- BAIKUNTHPUR

Dharambari PWD Path To Kasi Miya Ke Ghar Tak

ESTIMATED COST - RS.

1036500.00

SUBMITTED BY :-

EXECUTIVE ENGINEER
RWD (W) DIVISION
GOPALGANJ-2

Report

Name of Work

Motorable work of Dharambari PWD Path To

Kasi Miya Ke Ghar Tak

Estimated Cost

1036500.00 :-

Total length of Road

0.435 km

Description :- The present estimate has been farmed under the supervision of Assistant engineer in accordance with the order of Executive Engineer, RWD, WD Gopalganj-2, letter No. - 1574 dated 18-08-2020. The part of above mentioned road has been damaged due to heavy rain/flood. And due to this damage the transporation has been obstructed. The immediate motorable work is necessary in public interest. Villagers will be benefitted by the completion of this motorable work.

In the estimate there has been a provision of repairing the damaged part of the road & making it motorable by filling brickbats. In the context of post flood scenario there is still the flow of water which prevails through the damaged part of the road.

In this estimate the rate of raw materials and labour wages has been prepared after the analysis of new rate. This estimate is as per the specifications. The estimate is devoted to technical and administrative acceptance.

C 19/9/20

Detailed Estimate For Motorable Work in Road from Dharambari PWD Path To Kasi Miya Ke Ghar Tak damaged due to Heavy rain/flood for year 2020-2021

Sr.	Items	No.	L (M.)	W (M.)	D (M.)	Otv	11-14		
1	Providing brick bats billed in ditches including all cost of labour & material with all complete job.			,	D (W.)	Qty.	Unit	Rate	Amount
	CH - 300 M to 435 M	1	16.00	5.00	1.50	120.00	Мз		
		1	12.00	3.00	1.50	54.00	МЗ		
		1	8.00	2.00	1.30	20.80	M3		200
-		1	30.00	1.00	0.80	24.00	M3		
		1	20.00	2.00	0.80	32.00	МЗ		
		1	15.00	1.00	0.25	3.75	МЗ		
		1	18.00	2.50	1.40	63.00	МЗ		
_		1	18.00	3.00	0.55	29.70	МЗ		
		1	7.00	2.50	0.50	8.75	M3		
		1	3.00	2.00	0.35	2.10	M3	*	
		1	4.00	1.50	0.30	1.80	МЗ		
	Less for H.P.	0	0.00	0.00	0.00	0.00	МЗ	241214	1020081
						422.90	M3	2427.6 5	1026653.19
2	Providing & laying 1000 MM Dia NP3 Hume Pipe in single row -do-do- complete job.	0	2.50			0.00	М	27 44 56 4159.56	0.00 1 0200 \$1 3
									1026653.19
	Add 1 % Contigency	1							10266.53
					<u> </u>			Total	1036919.72
								Say	1036500.00

(2) 19/202D

A.F.

C 19/9/20

E.E. Supp 10.303 Le

Technically Appreved for R 10.303 law (Rupes Ten law Therty
Thomsand of Three Hyndred) only

Superintending Enguise

R W D Work, Circle-Stwart

P 14 10 1000