(FOR-2020)

N/W-Temporary Restoration of Road from NH-28 Putnito Borduyahi Ghat.

# Shedule XLV Form No. 134.

Raxaul. DIVISION

Ramgarwa SUB-DIVISION

# Measurement Book

723

पथानी / सिरिस जोड़ा

1

Name of work -
Situation of work -
Agency by which work is executed -
Date of measurement -
No. and date of agreement.
(These four lines should be repeated at the commencement of the measurements relating to each work.)

| Particulars | Details of actual measurement | | | | Contents of area |
|---|---|---|---|---|---|
| | No. | L. | B. | D. | |
| CH-2245 (ADR) | | | | | |
| Authority- E.E, RWD, Raxaul. | | | | | |
| Agency- Departmental. | | | | | |
| N/H - Temporary Restoration of Road | | | | | |
| from NH-28 Patni to Bardiyahi Ghat | | | | | |
| Date of entry- 21/8/20 | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | Measurement | | | | |
| (1) P/L of Brick Bat including | | | | | |
| light rammig - etc. | | | | | |
| CH 1500 to 2000 | | | | | |
| 25m x | 4.05m x | 0.50 m = | | | 50.625 |

21/8/20
JE

AE 21/8/20
Ramgarhwa

Continuation

Sch. XLV-Form No. 134

| Particulars | Details of actual measurement | | | | Contents of area |
|---|---|---|---|---|---|
| | No. | L. | B. | D. | |
| | | Abstract of Cost. | | | |
| (1) P/L of Brick Bats including Light ramming etc. | | | | | |
| TMB Dg. No. 1(1) | — | | 50.625 m³ | | |
| @ ₹ 2116.22/- | | | = ₹ | 107134=00 | |
| | | Total - ₹ | | 107134=00 | |

5/1/21 J.E

21/8/20 J.E

AE 5/1/21 Ramgarhwa

5/1/2021 Executive Engineer Rural Works Department Works Division Raxaul

Continuation

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, मोतिहारी।

पत्रांक 2769 (मु०) मोतिहारी / दिनांक 28-12-2020

प्रेषक :— कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, मोतिहारी।

सेवा में,

अधीक्षण अभियंता,
ग्रामीण कार्य विभाग,
कार्य अंचल, मोतिहारी।

विषय :— कार्य प्रमंडल रक्सौल अन्तर्गत वर्ष–2020 में बाढ़ एवं अतिवृष्टि के कारण क्षतिग्रस्त पथों को मोटरेबुल करने हेतु किए गए कार्यों की जाँच के संबंध में।

प्रसंग :— मु०अ०–04 (मु०) विविद (कार्य)–23–40 / 216–2789 पटना, दिनांक - 21.08.2020 एवं भवदीय कार्यालय आदेश ज्ञापांक--1344 दिनांक–28.08.2020

महोदय,

उपर्युक्त विषयक प्रसांगिक पत्र के अनुपालन में कार्य प्रमंडल, रक्सौल द्वारा उपलब्ध कराये गये मोटरेबुल पथों की सूची में अंकित पथों का अधोहस्ताक्षरी के द्वारा निरीक्षण किया गया। निरीक्षण के दौरान कार्य प्रमंडल, रक्सौल द्वारा प्रतिवेदित सभी पथों में मोटरेबुल का कार्य कराया गया है एवं वर्त्तमान यातायात चालू है।

सादर सूचनार्थ एवं अग्रेत्तर कार्रवाई हेतु समर्पित।

संलग्नः–निरीक्षण किए गए पथों की सूची।

विश्वासभाजन,

28/12/20

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, मोतिहारी।

28/12/20

# List of Road Damaged due to Flood 2020-21

| SlNo | Division | Road Name | Scheme | Road Status | Is Maintanance( Y/N) | Is Agreement( Y/N) | Length(In Km.) | Length of Damage Part Due to Flood in M | Actual Restoration Amount :(In Lac) | Remarks | Start Latitude | Start Longitude | End Latitude | End Longitude | Block |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | Raxaul | T01 NH-28A Ramgarhwa to Pakhnahiya Part of Length 9.20 Km of Ramgarhwa-Balthar via Sikata Road | MR | Completed | Yes | Yes | 5.2 | 519 | 13.79 | Badly Damaged | 26.877707 | 84.782244 | 26.877966 | 84.782244 | Ramgarhwa |
| 2 | Raxaul | Ramgarhwa - Sukhisemra (BR-11R-039) | PMGSY | Completed | No | No | 5.6 | 120 | 15.52 | Breach Near Pound | 26.884082 | 84.767253 | 26.883999 | 84.767253 | Ramgarhwa |
| 3 | Raxaul | Mishrauliya Loha pul to Vani Mishrauliya | MMGSY[Gen] | On Going | No | Yes | 1.48 | 40 | 3.91 | Breach near culvert. | 26.856772 | 84.808345 | 26.795765 | 84.808345 | Ramgarhwa |
| 4 | Raxaul | NH-28 Patni - Badriyahi Ghat | PMGSY-NEA | Completed | No | No | 5 | 25 | 1.07 | Breach | 26.835413 | 84.82028 | 26.835196 | 84.82028 | Ramgarhwa |
| 5 | Raxaul | NH-28A to Meena Tola (Part of Length 5.38 Km of NH28A to Laxmipur Road | MR | Completed | Yes | Yes | 3.8 | 107 | 3.08 | Breach | 26.877061 | 84.810369 | 26.874434 | 84.810369 | Ramgarhwa |
| 6 | Raxaul | NH-28A Road Semar Chowk to Gandhi Gram Kustha Colony | MMGSY[SC] | Completed | Yes | Yes | 1.13 | 75 | 2.86 | Breach & Badly Damaged | 26.860702 | 84.779436 | 26.860802 | 84.779436 | Ramgarhwa |
| 7 | Raxaul | NH-28 to Kharkatwa | PMGSY | On Going | No | Yes | 3 | 301 | 8.78 | Badly Damaged Near Pond | 26.905561 | 84.7976 | 26.913631 | 84.800462 | Ramgarhwa |
| 8 | Raxaul | NH-28A Path Chilijhapti To Sah Tola Katkenwa | MMGSY[Gen] | Completed | Yes | Yes | 2.3 | 179 | 7.15 | Breach & Badly Damaged | 26.813264 | 84.74192 | 26.80823 | 84.751044 | Ramgarhwa |
| 9 | Raxaul | NH-28A Road Murla To Sishbaniya Pokhra | MMGSY[SC] | Completed | Yes | Yes | 4.573 | 92 | 2.88 | Breach & Badly Damaged | 26.863209 | 84.789441 | 26.869867 | 84.781651 | Ramgarhwa |
| 10 | Raxaul | L041-Purushottampur to Balua | PMGSY | Completed | Yes | Yes | 3 | 105 | 4.23 | Breach & Badly Damaged | 26.884941 | 84.837248 | 26.885191 | 84.838505 | Ramgarhwa |
| 11 | Raxaul | Danhardiuli - unchidih (BR-11R-042) | PMGSY | Completed | No | No | 2.188 | 70 | 4.78 | Breach & Badly Damaged | 26.924685 | 84.807302 | 26.920371 | 84.814624 | Ramgarhwa |
| 12 | Raxaul | Pakhnahiya Konarawa to Kalikapur | MMGSY[Gen] | Completed | Yes | Yes | 2.506 | 65 | 1.78 | Badly Damaged | 26.893126 | 84.77557 | 26.93135 | 84.782481 | Ramgarhwa |
| 13 | Raxaul | T04 House of Umeshwar Singh to Baudha Harijan Basti | MMGSY[SC] | Completed | Yes | Yes | 1.17 | 118 | 3.24 | Badly Damaged | 26.897403 | 84.803945 | 26.89787 | 84.802588 | Ramgarhwa |
| 14 | Raxaul | Ramgarhwa - Singasni (BR-11R-281) | PMGSY | On Going | No | No | 6.032 | 105 | 2.7 | Badly Damaged | 26.869356 | 84.777737 | 26.87081 | 84.774889 | Ramgarhwa |
| 15 | Raxaul | Paknhia - Khonarwa (BR-11R-041) | PMGSY | On Going | No | Yes | 3.819 | 83 | 1.88 | Badly Damaged | 26.932071 | 84.777019 | 26.919618 | 84.774768 | Ramgarhwa |
| 16 | Raxaul | L038-NH-28 to Malahi Tola (BR-11R-420) | PMGSY | Completed | Yes | Yes | 2 | 49 | 1.93 | Breach & Badly Damaged | 26.878601 | 84.804409 | 26.878449 | 84.804362 | Ramgarhwa |
| 17 | Raxaul | Pakhnahia - Garhwa (BR-11R-040) | PMGSY | Completed | No | No | 7.082 | 53.5 | 1.25 | Badly Damaged | 26.913007 | 84.763809 | 26.89494 | 84.733856 | Ramgarhwa |
| 18 | Raxaul | NH-28 A to Laxmipur Road. | MMGSY OLD | Completed | No | No | 5.38 | 37 | 1.25 | Badly Damaged | 26.86617 | 84.823224 | 26.866173 | 84.823278 | Ramgarhwa |
| 19 | Raxaul | L034-L027 Triveni to Bherihari (VR34) | PMGSY | Completed | Yes | Yes | 4.732 | 67 | 1.8 | Causeway Badly Damaged | 26.849351 | 84.742007 | 26.948346 | 84.741633 | Ramgarhwa |

28/12/XY
E.E. (R.W.D.)
Motihari