

Name to work— 1

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work—	Til kora ward no				
	-12 me gulas chandra				
	Gadhav ko shaw se				
	barihat me shaw tak.				
Block—	Murliganj				
Agency—					
	M.D— 05/01/2021				

	Initial	Final	At	Bill
Item - (1)	Providing bricks bats			
	filled in ditches portion-			
	1x	10	3.25	0.30 = 9.75
	3x	30	3.50	0.90 = 283.50
	1x	22	3.50	0.60 = 46.20
	1x	30	3.25	0.70 = 68.25
	1x	15	3.40	0.75 = 38.25
	7x	30	3.40	0.35 = 249.9
	1x	25	3.25	0.40 = 32.50
	1x	30	3.25	0.30 = 29.25
	1x	25	3.50	0.40 = 35
				792.6
				100

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Item ②	sand filling over bricks bats				
	12	30	3.25	0.15	175.5
	1	4	3.25	0.15	9.75
	1	15	3.25	0.15	7.31
	1	25	3.25	0.15	12.18
	1	25	3.25	0.15	12.18
					<u>216.92</u> M ³
A. K. K. K. 05/10/2021 5/1					

Abstract of cost

Item no ①	P/V Bricks bats in ditches portion				
	V.T.M.B.P. No - ①				
	Item no - ① - 792.6 M ³				
	@ 1856.19/M ³ - 5				
					1477126.2
Item ②	P/V L/sand filler over Bricks bats				
	V.T.M.B.P. No - ②				
	Item no - ② - 216.92 M ³				
	@ 554.03/M ³ - 120/80				
					1591396.2

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B.F	15913	96.00
Add C.S.T.	127			190968	=.00
Add Excess 1%				15914	=.00
S.F				87330	=.00
				18,85608	=.00

~~A. Kumari~~
05/01/2021
J.G

~~A. Kumari~~
05.01.21
J.G

~~A. Kumari~~
31/11

- Continuation

Inspection Report for Flood Damage work

Date:-

- 1 Name of PIUS :- Madhepura
2 Name of Block :- MYSHIHATI
3 Name of Road :- TILKORA ward no-12 one canal ab chandra yodhav ke gharse banhar myshati talc .

A. For Road

- 1 Damage Location/Chainage :-
2 Damage Length :- 0.555 km
3 Nature of damage :- water logging due to heavy rainfall.
4 Details of Restoration Works :-
i Material being used in Restoration works:-
ii Equipments/Tools being used in Restoration works :-
iii Procedure taken up in Restoration works :-
iv Restored Length :- 0.55 km.
- } Bricks bats, local sand.

B. For Bridge

- 1 Damage Location/Chainage :-
2 Damage Length :-
3 Nature of damage :-
4 Details of Restoration Works :-
i Material being used in Restoration works:-
ii Equipments/Tools being used in Restoration works :-
iii Procedure taken up in Restoration works :-
iv Restored Length :-

A. K. Singh
JE 30/12/22

A. K. Singh
30.12.2022
AE

[Signature]
30/12/22
EE

[Signature]
Signature

(Name of inspector)
EXECUTIVE ENGINEER
RWD (M) DIVISION, UDAKISHUNGAR