

Inspection Report for Flood Damage work

Date:- 10-01-2021
 1 Name of PIUS :- Er Shailendra Kumar
 2 Name of Block :- Shankarpur
 3 Name of Road :- Gulftung To Klap Tola

A. For Road

1 Damage Location/Chainage :- 1.800, 2.100
 2 Damage Length :- 0.010 km
 3 Nature of damage :- Each other shoulder Recell built
 4 Details of Restoration Works :-
 i Material being used in Restoration works:-
 ii Equipments/Tools being used in Restoration works :-
 iii Procedure taken up in Restoration works :-
 iv Restored Length :- 0.008 km

Backs Bat

B. For Bridge

1 Damage Location/Chainage :-
 2 Damage Length :-
 3 Nature of damage :-
 4 Details of Restoration Works :-
 i Material being used in Restoration works:-
 ii Equipments/Tools being used in Restoration works :-
 iii Procedure taken up in Restoration works :-
 iv Restored Length :-

JE
N Kumar
30-12-20

AE
30-12-20

EE
30/12/20

Signature
30/12/20

(Name of Inspector)

EXECUTIVE ENGINEER
RWB (W) DIVISION UDAKISHUNGAM

↑

No. and date of agreement.

[illegible]

$$= 49.50 \text{ m}^3$$

~~N. Kumar~~
05-01-2021
J-E

05.01.21
AE

~~Des~~

ABSTRACT OF COST

Sch. XLV—Form No. 134

2

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① providing and laying of Bricks but obtained from Chimney with mechanical means —					
Qty vide TMB P ①					
$49.50 \text{ m}^3 @ \text{Rs } 1856.19/\text{m}^3 = \text{Rs } 91881.55$					
Seigniorage Fees Rs 5262.00					
Add @ 12% GST = Rs 11025.79					
Add @ 1% L Cess = Rs 918.82					
$= \text{Rs } 109088.15$					
Say Rs 109088.00					
Noted 05-01-2021 J.E. By 05-01-21 BE By 11					