

(These four lines should be repeated at the commencement of the measurements relating to each work.)

[illegible]

① providing and laying of
brick but obtained from
Chimney with machonical
means with all spreading
grading to required —

$1 \times 4.60 \text{ m} \times 1.90 \times 0.25 =$	2.185 m^3
$1 \times 3.80 \text{ m} \times 2.50 \times 0.28 =$	2.66 m^3
$1 \times 5.70 \text{ m} \times 3.40 \times 0.22 =$	4.264 m^3
$1 \times 8.20 \text{ m} \times 2.60 \times 0.25 =$	5.33 m^3
$1 \times 7.80 \text{ m} \times 2.40 \times 0.26 =$	4.867 m^3
$1 \times 9.80 \text{ m} \times 4.80 \text{ m} \times 0.32 =$	15.053 m^3
$1 \times 8.80 \text{ m} \times 5.20 \text{ m} \times 0.28 =$	12.813 m^3
$1 \times 8.00 \text{ m} \times 2.50 \text{ m} \times 0.22 =$	4.40 m^3
$1 \times 7.80 \text{ m} \times 3.50 \text{ m} \times 0.225 =$	6.143 m^3
$1 \times 3.00 \text{ m} \times 5.30 \text{ m} \times 0.25 =$	3.975 m^3
$1 \times 25.80 \text{ m} \times 2.80 \text{ m} \times 0.175 =$	12.642 m^3

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1	6.80m	5.60m	0.325	$12.376m^3$
	1	8.30m	3.40m	0.35	$9.877m^3$
	1	8.50m	3.20m	0.225	$6.12m^3$
	1	9.50m	4.90m	0.30	$13.965m^3$
	1	14.90m	4.70m	0.275	$19.258m^3$
	1	4.00m	2.50m	0.25	$2.50m^3$
	1	15.20m	4.40m	0.25	$16.72m^3$
	1	10.50m	2.60m	0.225	$6.143m^3$
	1	5.30m	2.30m	0.175	$2.133m^3$
	1	14.5m	2.20m	0.22	55.418
	1	58.80m	4.30m	0.25	$63.21m^3$
	1	28.50m	4.20m	0.21	25.137
	1	4.60m	2.50m	0.225	2.588
	1	5.3m	2.60m	0.25	3.445
	1	35.30m	2.70m	0.20	19.062

1	7.40m	4.90m	0.225	8.159
1	3.7m	2.70m	0.175	1.748
1	10.20m	4.30m	0.25	10.965
1	6.00m	2.20m	0.225	2.970
1	5.9m	4.10m	0.23	$5.564m^3$
1	6.90m	3.80m	0.225	$5.901m^3$
1	4.40m	3.20m	0.175	2.464
1	7.20m	2.50m	0.15	$2.70m^3$
1	21.80m	2.20m	0.175	$8.393m^3$
1	37.60m	4.70m	0.15	26.508
1	11.70m	2.50m	0.225	6.581
1	8.50m	2.30m	0.175	$3.421m^3$
1	7.20m	5.00m	0.25	$9.00m^3$
1	20.00m	5.40m	0.20	$21.60m^3$
1	12.00m	6.00m	0.30	$21.60m^3$
1	7.90m	2.50m	0.175	$3.456m^3$

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1	8.10m	1.50m	0.175	= 2.126
	1	47.00m	5.20m	0.18	= 43.992
	1	12.00m	2.50m	0.175	= 5.250
	1	32.40m	3.50m	0.20	= 22.68
	1	5.00m	3.90m	0.225	= 4.388
	1	16.00m	1.50m	0.175	= 4.20m ³
	1	9.10m	2.30m	0.18	= 3.767
	1	6.20m	2.00m	0.175	= 2.17
	1	22.40m	4.40m	0.26	= 25.626
	1	4.90m	3.20m	0.225	= 3.528
	1	23.80m	4.40m	0.25	= 26.18
	1	161.70m	6.50m	0.25	= 262.763
	1	13.40m	4.30m	0.225	= 12.965
	1	31.50m	4.90m	0.28	= 38.588
	1	50.40m	4.80m	0.225	= 54.432

	1	7.50m	2.50m	0.175	= 3.281
	1	6.30m	2.20m	0.22	= 3.049
	1	34.50m	3.80m	0.225	= 29.498
	1	11.4m	3.80m	0.225	= 9.747
	1	5.50m	2.10m	0.25	= 2.888m ³
	1	34.60m	1.80m	0.20	= 12.456
	1	40.20m	2.00m	0.175	= 14.070
	1	7.90m	4.20m	0.225	= 7.466m ³
	1	9.60m	2.50m	0.25	= 6.00m ³
	1	33.50m	2.00m	0.26	= 17.420
	1	5.10m	4.80m	0.31	= 7.589
	1	12m	1.60m	0.275	= 5.280
					= 1104.707m ³

N. Kumar
05-01-2021
J.E

AE
05-01-21
AE

Continuation

511

ABSTRACT OF COST

Sch. XLV—Form No. 134

4

[illegible]

~~11/11/2022~~
~~05-01-2022~~
~~15/17~~

05.01.21

Handwritten signature: *A. B. ...*

Inspection Report for Flood Damage work

Date:- 10-01-2021

1 Name of PWS :- ex Shalendra Kumar

2 Name of Block :- Shankarpur

3 Name of Road :- Bawli Nagar, the middle system

A. For Road

1 Damage Location/Chainage :- 0.352, 2.80, 3.30, 4.80, 5.60, 6.10

2 Damage Length :- 0.352 km

3 Nature of damage :- earthen shoulder and Road cut

4 Details of Restoration Works :-

i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works:-

iii Procedure taken up in Restoration works :-

iv Restored Length :- 1.254 km

B. For Bridge

1 Damage Location/Chainage :-

2 Damage Length :-

3 Nature of damage :-

4 Details of Restoration Works :-

i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :-

JE
30-12-20

AE
30-12-20

EE
30/12/21

Signature
30/12/21

(Name of Inspector)

EXECUTIVE ENGINEER
ROADS DIVISION