



# ABSTRACT OF COST

Sch. XLV—Form No. 134

2

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① providing and laying of brick lat obtained from chimney with mechanical means — @ vide T.M.B.P ① $244.44 \text{ m}^3 @ \text{Rs } 18.56.19/\text{m}^3 = \text{Rs } 416603.95$ signage fees = Rs 23858.00 Add @ 12% GST = Rs 49992.47 Add @ 1% Labour cess = Rs 4166.04 = Rs 494620.46 Say Rs 494620.00					
<del>NKM 02</del> 05-01-2021 S.E.					
<del>AE</del> 05-01-21 AE					
<del>AE</del> 05-01-21 AE					

  
 5/1

Inspection Report for Flood Damage work

Date:- 10-01-2021

1 Name of PIUS :- 87 Shalendra Kumar

2 Name of Block :- Shankarpur

3 Name of Road :- Shankarpur to Bafkon pass

**A. For Road**

1 Damage Location/Chainage :- 0.750, 4.900

2 Damage Length :- 0.141 k.m

3 Nature of damage :- Eastern shoulder and Road crown

4 Details of Restoration Works :-

i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works :- *Backhoe*

iii Procedure taken up in Restoration works :-

iv Restored Length :- 0.106 k.m

**B. For Bridge**

1 Damage Location/Chainage :-

2 Damage Length :-

3 Nature of damage :-

4 Details of Restoration Works :-

i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :-

JE  
*N Kumar*  
30-12-20

AE  
*R*  
30-12-20

EE  
*R*  
30-12-20

Signature  
*(Signature)*

(Name of Inspector)

**EXECUTIVE ENGINEER**  
RWD (M) DIVISION, UDAKISHUNGAM