

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1	24.90	2.40	m x 0.22	= 13.147 m ³
	1	2.50	m x 3.20	x 0.225	= 1.80 m ³
	1	11.40	m x 3.60	m x 0.25	= 10.26 m ³
	1	87.80	m x 3.75	m x 0.20	= 65.85 m ³
	1	12.90	m x 4.30	m x 0.25	= 13.868 m ³
	1	18.50	m x 4.20	m x 0.225	= 17.483 m ³
	1	3.10	m x 2.60	m x 0.225	= 1.814 m ³
	1	11.70	m x 4.30	m x 0.225	= 11.32 m ³
	1	56.60	m x 3.50	m x 0.20	= 39.62 m ³
	1	106.00	m x 4.60	m x 0.25	= 121.90 m ³
					= 652.174 m ³
<u>N. Kumar</u> 05-01-21 J.E. <u>B.</u> 05-01-21 A.E. <u>20</u> 51					

ABSTRACT OF COST

Sch. XLV—Form No. 134

3

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① providing and laying of bricks but obtained from chimney with mechanical means with all spreading grading —					
city side TMBP ②					
$652.17 m^3 @ Rs 1856.19/m^3 = Rs 1210560.97$					
Seigniorage Fees = Rs 69326.00					
Add @ 12% GST = Rs 145267.32					
Add 1% L. cess = Rs 12105.61					
= Rs 1437259.89					
Say Rs 14,37,260.00					
① Kumar 05-01-2021 AE 25/1					

Inspection Report for Flood Damage work

Date:- 10-01-2021

- 1 Name of PWS :- By Shalender Kumar
- 2 Name of Block :- Shankapur
- 3 Name of Road :- Shankpur to Shankapur

A. For Road

1 Damage Location/Chainage :- 2.250, 2.480, 3.500, 4.30, 4.40, 5.70

2 Damage Length :- 0.550 K.m

3 Nature of damage :- Earthken and Road cut

4 Details of Restoration Works :-

i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :- 0.716 K.m

B. For Bridge

1 Damage Location/Chainage :-

2 Damage Length :-

3 Nature of damage :-

4 Details of Restoration Works :-

i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :-

JE
30-12-20

AE
30-12-20

EE
30-12-20

Signature
30/12/20

(Name of Inspector)

EXECUTIVE ENGINEER
RWD (W) DIVISION, UDAKISHUNGAM