

Inspection Report for Flood Damage Work

Date:-

1 Name of PUs :- Gyan Vihar

2 Name of Block/Road :- Block 1 & 2 (to include nearby Block 3 & 4)

(A) For Road: ✓

1. Damage Location/Chainage :- 0.62km, 0.77km, 0.78km, 1.25km, 1.50km,
2. Damage Length :- 457.3m (0.4573km) 1.25km, 2.00km, 2.50km,
3. Nature of Damage :- 2.50km
4. Details of Restoration Works :- (Length 2.50km)
- (i) Material being used in Restoration works :- bricks, etc.
- (ii) Equipment's/Tools being used in Restoration works :-
- (iii) Procedure taken up in Restoration works :-
- (iv) Restored Length :- 0.4573km

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
- (i) Material being used in Restoration works :-
- (ii) Equipment's/Tools being used in Restoration works :-
- (iii) Procedure taken up in Restoration works :-
- (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE
Road works Division
Muzaffarpur Circle

GENERAL ABSTRACT

Name of Road Barheta Chowk to Bhulane PMGSY Bharat Sah House

District Muzaffarpur

Block Bochaha

Division Muzaffarpur East-2

Length of Road (in Km)

3.025 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	14.575
2	Sand Filling	0.770
3	H.P.	0.591
4	Bamboo Piles	0.770
	GRAND SUB TOTAL	15.566
TOTAL COST OF PROJECT IN LACS =		15.566

[Signature]
JE
RWD

[Signature]
AE
RWD

[Signature]
EE
RWD

Technically approved for Rs 15.566 lac

(Rupees fifteen lac fifty six thousand six hundred only)

[Signature]
16-1-21
अधीक्षण अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुजफ्फरपुर