Inspection Report For Flood Damage Work

Date:

1 Name of PIUs: GTONAL NANJ-2

2 Name of Block/Road: BADKUNTHPUR/ WAMHARD BANDH WATT RAY ICE TOLA TO

A For Road

SONWALIYA PASCHIM TOLA

1 Damage Location / Chainage:

220 m to 450 m

2 Damage Length:

234 m

3 Nature of Damage:

Heavy Rain / Flood.

4 Details of Restroration Works:

i. Material being used in Restoration Works:

Brick Bats

ii Equipments / Tools being used in Restoration Works: DCB, Tractor, Trols, Belaka, Shawal

iii Procedure taken up in Restoration Works:

Mas

iv Restored Length:

23400

B For Bridge

NIA

- 1 Damage Location / Chainage:
- 2 Damage Length:
- 3 Nature of Damage:
- 4 Details of Restroration Works:
 - i. Material being used in Restoration Works:

ii Equipments / Tools being used in Restoration Works:

jji Procedure taken up in Restoration Works:

iv Restored Length:

Phil 2020

Demis og govo

EE

Signature 5

(Name of Inspector)







ग्रामीण कार्य विभाग

Rural Works Department, Govt. of Bihar

FLOOD DAMAGED REPAIR (F.D.R.)

STATE :- BIHAR

DISTRICT :- GOPALGANJ

BLOCK :- BAIKUNTHPUR

Gamhari Bandh Gati Rai Ke Tola to Sonwaliya Paschim Tola

ESTIMATED COST - RS.

-2500000.00-2344800 coo

SUBMITTED BY :-EXECUTIVE ENGINEER RWD (W) DIVISION GOPALGANJ-2

Report

Name of Work

:- Motorable work of Gamhari Bandh Gati Rai Ke

Tola to Sonwaliya Paschim Tola

Estimated Cost

:- 2500000.00 hs 2344800 200

Total length of Road

:- 0.450 km

Description :- The present estimate has been farmed under the supervision of Assistant engineer in accordance with the order of Executive Engineer, RWD, WD Gopalganj-2, letter No. - 1574 dated 18-08-2020. The part of above mentioned road has been damaged due to heavy rain/flood. And due to this damage the transporation has been obstructed. The immediate motorable work is necessary in public interest. Villagers will be benefitted by the completion of this motorable work.

In the estimate there has been a provision of repairing the damaged part of the road & making it motorable by filling brickbats. In the context of post flood scenario there is still the flow of water which prevails through the damaged part of the road.

In this estimate the rate of raw materials and labour wages has been prepared after the analysis of new rate. This estimate is as per the specifications. The estimate is devoted to technical and administrative acceptance.

Blul 11912010 J.E.

A.E.

E.E.

Detailed Estimate For Motorable Work in Road from Gamhari Bandh Gati Rai Ke Tola to Sonwaliya Paschim Tola damaged due to Heavy rain/flood for year 2020-2021

				2021					
1	Items	No.	L(M.)	W (M.)	D (M.)	Qty.	Unit	Rate	Amount
1	Providing brick bats billed in ditches including all cost of labour & material with all complete job.								
	CH - 220 M to 450 M	1	15.00	3.00	1.60	72.00	МЗ		
		1	7.00	1.00	2.00	14.00	МЗ		
		1	25.00	4.00	2.00	200.00	МЗ		
ļ		1	7.00	1.50	2.50	26.25	МЗ		
ļ		1	-20.00	-1.35	2.00	54.00	МЗ		
		1	30.00	1.00	3.00	90.00	МЗ		
		1	14.00	1.50	2.50	52.50	МЗ		
		1	29.00	1.55	3.00	134.85	МЗ		
		2	30.00	2.00	1.20	144.00	МЗ		
		1	-25.00-	1.50	3.00	-112.50	МЗ		
		1	20.00	1.70	1.80	4 0x32 61.20	МЗ		
		1	-5.00	-4.00	2.00	40:00	МЗ		
		1	4.00	4.00	0.80	12.80	МЗ	E34 - 3- 4 1	
		1	3.00	3.75	0.50	5.63	M3		
	Less for H.P.	0	1.23	1.23	0.95	0.00	МЗ	2412-11	130681/20
_						_1019,73	M3	2427.65	2475535.40
	Providing & laying 1000 MM Dia NP3 Hume Pipe in single row -do-do- complete job.	0	2.50			95635	м	4159.56	232167019. 0.00 232167019
-	Add to the second	-	-	-				2306811	-2475535.40
	Add 1 % Contigency	-				1321889		23068 Total	- 24755.35 - 2500290.75
-		-				7001		Say	2500290.75 2500000.00

Seng R 23. 299 Cen

Teolisically Approved for R. 23. 299 la (Ruper Twenty Three land Twenty Nine Thousand to Nine 1-14udral with Three land

R W D Work, Circle-Siwan