

# FIELD INSPECTION REPORT

GTSNY

Date of Inspection:	21/12/20	District:	Motihari
Division:	Pakharidagel	Length(Km):	1.20
Name of Road:	Bankatba bank to Pakharidagel Thikha road		
Scheme/Programme:	Maintenance ✓		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance		

S No.	Parameters to be Checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank /slope & raincuts if any	Yes/No
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	S/SRI/U
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U
3	<b>Road Furniture</b>	
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No
3	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Name:  
Designation:

*[Signature]*  
21/12/20  
PE

*[Signature]*  
21/12/20  
DE