

FIELD INSPECTION REPORT

Date of Inspection :	16/11/21	District:	Nelands
Division :	Rajsh	Length (km):	0.32 km
Name of the Road:	Loyu To Akuna West to 9		
Scheme Programme:	MAINTENANCE	Road Id No.:	MMUSY (GEN)
Package No.:			
Status of the Project:	☒ Ongoing ☐ Completed ☐ Under Maintenance ongoing		
Work is a case of:	☐ New Connectivity ☐ Up gradation ☐ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No ☒
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ☒
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings Slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

Ranobhresh Kumar

NAME: JE
Rajsh / Brn

16/11/21
(Signature)