

FIELD INSPECTION REPORT

Date of Inspection :	6.01.2021	District:	Nalanda
Division :	Roads	Length (km):	0.800
Name of the Road:	Murgama chabilapur Path to murgam kohim Teh		
Scheme/Programme:	MAINTENANCE	Road Id No.:	Ongoing
Package No.:			NA
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	☒ New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

5

Satisfactory but requires improvement (SRI)

—

Unsatisfactory (U)

—

(Signature)

NAME: Shiva Kumar Gubla
A-EL (Ben)