



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

FDR



RESTORETION FOR ANJANI SE KAPSA TAK PATH NIRMAN

DISTRICT	:-	Chapra	
DIVISION	:-	Sonpur	
BLOCK	:-	Parsa	
TOTAL LENGTH OF ROAD	:-	1.600	KM
TOTAL COST OF CONSTRUCTION	:-	4.668	Lac
TOTAL COST OF PROJECT	:-	4.668	Lac


FDR (2020-2021)


प्रतिवेदन

प्रमंडल का नाम:-	ग्रामीण कार्य विभाग, कार्य प्रमंडल सोनपुर
पथ का नाम:-	अंजनी से कपसर तक
पथ की लम्बाई:-	1.600 कि०मी०
प्राक्कलित राशि:-	4.668 लाख
प्रखंड:-	परसा
जिला:-	सारण

प्रस्तुत प्राक्कलन सारण जिला अन्तर्गत परसा प्रखंड के अंजनी से कपसर तक पथ बाढ़ से क्षतिग्रस्त (FDR) पथांश का यातायात पुर्नस्थापन (Motrable) कार्य कराकर प्राक्कलन तैयार किया गया है। इस वर्ष अचानक अत्यधिक बाढ़ आने के कारण पथ में जगह जगह कटाव हो गया एवं पथ क्रस्ट बह गया जिससे आवागमन बाधित हो गया, चुनाव के मध्य नजर पथ का तत्काल मरम्मत के लिए पथांश में Brick Bats एवं मिटी भरकर कटाव से बचाव का कार्य करते हुए यातायात को पुर्नस्थापित किया गया।

पथ मरम्मत कार्य का प्राक्कलन वर्तमान अनुसूची दर पर ही तैयार किया गया है। प्राक्कलन की स्वीकृति अपेक्षित है।


कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल परसा


सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल परसा


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल सोनपुर

Inspection Report For Flood Damage Work

Date :- 03-12-20

1 Name Of PIUs :- Executive Engineer, RWD, WORKS DIVISION-SONPUR

2 Name Of Road :- Restoration For Anjani Se Kapsa Tak Path Nirman

3 Name Of Block Parsa

A.FOR ROAD

1 Damage Location/Chainage :- CH-30 M TO 37 M CH-150 M TO 166 M
CH-840 M TO 846 M LCH-1000 M TO 1012 M

2 Damage Length m :- 41

3 Nature Of Damage :- Wash Out Of Road Crust With Embankment

4 Details Of Restoration :-

i Material Being Used In Restoration :- EARTHWORK / BRICK BATS

ii Equipment/Tools Being Used In Restoration Works Tracter, Loader, Hambar

iii Procedurre Taken Up In Restoration Works :- Filling Of Brick Bats In Wash Out Portion
Of Road Crust And Supporting By
Earthwork In Embankment

iv Restored Length m :- 41

B.FOR ROAD

1 Damage Location/Chainage :-

2 Damage Length :-

3 Nature Of Damage


4 Details Of Restoration :-


i Material Being Used In Restoration :-


ii Equipment/Tools Being Used In Restoration Works :-


iii Procedurre Taken Up In Restoration Works :-

iv Restored Length :-


Signature Of JE/AE/EE


3/12/20


07/12/20


Signature
(Name Of Inspector)


FDR


GENERAL ABSTRACT OF COST

Block:-- Parsa District:- Chapra
Length of Road:-- 1.600 KM
Name of Road:-- Restoration For Anjani Se Kapsa Tak Path Nirman

SL. No.	Item of Work	Amount
A	TOTAL COST OF CONSTRUCTION :	4.668 Lacs
	TOTAL :	4.668 Lacs



Junior Engineer


Asstt. Engineer


Executive Engineer

T/A Approved for Rs-4.668 lacs (Rupees Four Lacs Sixty Six Thousand eight hundred) only

SE
RWD


S.E. Chapra

GENERAL ABSTRACT OF COST FOR FDR OF ROAD

NAME OF ROAD : Restoration For Angant Se Kapsa Tak Path Birman
DISTRICT : Chapra
BLOCK : Patna
DIVISION : Kaimur
LENGTH OF ROAD (in Km) : 1.000

Sl. No.	DESCRIPTION	Amount	1 % Labour Cost	12 % GST	GROSS AMOUNT (LAHS)
PART A	INITIAL RECTIFICATION INCLUDING SURFACE RENEWAL				
1	EARTHWORK, BRICK BATS & NP3 1000 Dia.	4.131	0.041	0.496	4.668
TOTAL COST OF PROJECT IN LAHS		4.131	0.041	0.496	4.668

JE
RWD

AE
RWD

EE
RWD

