

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- pmsy me siya saran mahto ke ghar to susta & kapil Ram ke Dery.


(A) For Road: ✓

- 0.240km, 0.520km, 0.260km, 0.320km, 0.410km, 0.480km
pmsy me siya saran mahto ke ghar to susta B. in
kapil Ram ke dery. 0.520km
274.6m (0.2746km) (Length 0.521km)
1. Damage Location/Chainage :-
 2. Damage Length :-
 3. Nature of Damage :-
 4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- brick bats.
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.2746km

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE
RWD Work Division
muzaffarpur East-1

GENERAL ABSTRACT

Name of Road PMGSY Me Siya Saram Mahto ke Ghar to Susta B Kapil Ram ke Dera

District Muzaffarpur

Block Gaighat

Division Muzaffarpur East-2

Length of Road (in Km) 0.571 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	19.124
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	19.124
TOTAL COST OF PROJECT IN LACS =		19.124


JE
RWD


AE
RWD


RWD

Technically approved for Rs 19.124 lac
(Rupees Nineteen lac Twelve thousand four
hundred only)


16.1.24
प्रमाण कार्य विभाग
कार्य अंचल, मुजफ्फरपुर