## FIELD INSPECTION REPORT

Date of Inspection:					
Division: Kishangani-1			District: Kishanganj		
Name of the Road: The North Length (km): 1					
Scheme/Progress to Ramor tola.					
Package No.:					
Status of the Duct.					
Work is a see s		Ongoing/Completed /Under Maintenance			
S1. No	. No				
1.	Dayone and			Remarks	
a)	Road Junction Condition			S/U	
b)				<b>√</b> 8/U	
c)	Condition of Surfacing			✓S/U	
d)	Riding Quality			<i>-</i> 8/U	
	Road Camber			<i>U</i> 5/U	
e)	Whether free from defects such as visible cracks, exposed aggregates Yes/No				
5)	in case of CC Pavement.				
f)				Yes/No	
g)				Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting			S/SRI/U	
<b>b</b> )	Condition of Abutment & Wing walls, slab in RCC culverts			LS/SRI/U	
c)	Condition of railings/Slab/approach for Bridges			<i>S</i> /SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m			Yes/No	
	stones/Pavement road markings are provided and maintained				
4.	Compliance History				
a)	Status of ATR's 8	& any others	Na	ATR.	

Overall Rating:

Satisfactory(S)	۱۵۰
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

(Signature)

NAME: Sanjeev Kumar Paswan
J.E, RWD, Terhagachh