FIELD INSPECTION REPORT

	ETION REPORT		
Date of Inspection:	21-1-2021 District Kill	<u> </u>	
Division: Kishangani-1			
Deligitifiiii. 1. C.O.			
Scheme/Programme: MM(05V.			
Packago No.			
Road Id No.:			
Work is a case of:	Ongoing/Completed /Under Maintenance		
S1 No			
1. Pavement	Parameters to be checked Remarks		
	Road Junction Condition		
	Condition of Surfacing		
	Riding Quality		
-	Road Camber		
	Whether free from defects such as visible cracks, exposed aggregates		
	in case of CC Pavement.		
f) Contraction	Contraction Joints Provided or not (CC Pavement) 목es/No		
g) Compaction	Compaction of flank / shop & raincuts if any		
2. Cross Drain	Cross Drainage		
a) Condition o	Condition of head walls in Hume pipe culverts including its Painting S/SF		
b) Condition o	Condition of Abutment & Wing walls, slab in RCC culverts		
c) Condition o	Condition of railings/Slab/approach for Bridges		
3. Road Furnit	Road Furniture		
a) Whether sig	n boards/informatory/cautionary Board/km & 200m	∠Yes/No	
stones/Pave	stones/Pavement road markings are provided and maintained		
4. Compliance	Compliance History		
a) Status of AT	R's & any others	101 ATR.	

Overall Rating:

Satisfactory(S)	(60,)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

(Signature)

NAME: Sanjeev Kumar Paswan
J.E, RWD, Terhagachh