FIELD INSPECTION REPORT

ate of In	spection: 19	91	21		District: Somathbox	a and desiration to the second specialists
ivision :	Sanaskh				Length (km):	
ame of t		52	to Pol	la 1	churdgah Somnaha.	
cheme/P	rogramme:		AINTENA			
ackage N	vo.:				Road Id No.:	and a second section of the second
				mpleted/Under Maintenance		
York is a	case of:	No	w Connect	tivity/U	p gradation/ Maintenance	-
l. No.	in the second	া সংগ্ৰ	Parame	iers lo	be checked	Remarks
1.	Pakement :	1		2.3		n. desc
a)	Road Junction	ı cor	-	ئىنى سىدىنىنىنىدىكىنى <u>.</u>		√ \$/U
b)	Condition of Surfacing					~\$/U
c)	Riding Qualit	y	Bernadiana, dain sala bila bira, pasa		Vi Vi	45/U
d)	Road Cambe	r				SIU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/No.					Yes/No
f)	Contraction Joints provided or not (CC Pavement) Yes/No					Yes/No
g)	Compaction	of fl	ank/slope &	& raincu	its if any	Yes/No
2.7	Commit	age				
a)	Condition of	hea	d walls in H	lume pi	pe culverts including its painting	_8/SRI/U
b)	Condition of	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U				
c)	Condition of	rail	ings/slab/ap	proach	for Bridges	√S/SRI⁄U
3.3	Rome Chert	ture		1.1.11		
a)	Whether signstones/Paver	gn t men	oards/infor road mark	matory/ ings are	/cautionary Board/km & 200m provided and maintained	Ýes/No
	Compliant	Hi	itory≱⊷ †	1-4		Hair
a)	Status of A7	rR's	& any other	ers		40

Satisfactory (S)	.<
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	
Unsatisfactory (U)	-

(Signature)

NAME: Granton Day