FIELD INSPECTION REPORT

| D | TIELD INSPECTION REPORT | | |
|--|--|---------------|--|
| Date of | Inspection: 21 to 100 REPORT | | |
| Date of Inspection: 21-1-2021 District: Kishanganj | | | |
| Name of the Road: Charles Length(km): O+ GO | | | |
| Scheme/programmy Touch to Thimbis and de have ma soon to be | | | |
| Package No.: | | | |
| Status of the D | | | |
| Work is a see a se | | | |
| S1. No Naintenance | | | |
| 1. | Parameters to be checked | Remarks | |
| a) | Road Junction Condition | └ \$/U | |
| b) | Condition of S. S. | ∪S/U | |
| c) | Condition of Surfacing | -S/U | |
| d) | Riding Quality Road Camber | <i>∽</i> \$/U | |
| e) | | <i>⊸</i> 8/U | |
| ς, | Whether free from defects such as visible cracks, exposed aggregates | Yes/No | |
| £/ | in case of CC Pavement. | | |
| f) | Contraction Joints Provided or not (CC Pavement) | Yes/No | |
| g) | Compaction of flank / shop & raincuts if any | Yes/No | |
| 2. | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its Painting | ~S/SRI/U | |
| p) | Condition of Abutment & Wing walls, slab in RCC culverts | S/SRI/U | |
| c) | Condition of railings/Slab/approach for Bridges | -S/SRI/U | |
| 3. | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m | Yes/No | |
| | stones/Pavement road markings are provided and maintained | | |
| 4. | Compliance History | | |
| a) | Status of ATR's & any others | ATR. | |
| | | | |

Overall Rating:

| Satisfactory(S) | |
|---|--|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory(U) | |

(Signature)

NAME: Sanjeev Kumar Paswan
J.E, RWD, Terhagachh