FIELD INSPECTION REPORT

Date of Inspection: 21-1-2021					
Division: Kishanganj-1 Division: Kishanganj-1 Longth (Longth)					
Name of the D					
Scheme/Programme Lo 43 to Rijaul hak bhase korteta Thunki.					
Package No.:					
Status of the Pro: Road Id No.:					
Work is	a case of:	Ongoing/Comple	eted /Under Maintenance —		
S1. No	1. No New Connectivity/ Up gradation / Maintenance				
1.	Parameters to be checked Pavement			Remarks	
a)				US/U	
b)	Road Junction Condition			U 5/U	
c)	Condition of Surfacing			لك\U	
d)	Riding Quality			√5/U	
	Road Camber			√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates			Yes/No	
	in case of CC Pavement.				
f)	Contraction Joints Provided or not (CC Pavement)			Ƴés/No	
g)	Compaction of flank / shop & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting			~\$/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts			ംS/SRI/U	
c)	Condition of railings/Slab/approach for Bridges			S /SRI/U	
3. '	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m			-Yes/No	
N 5	stones/Pavement road markings are provided and maintained				
4.	Compliance History				
a)	Status of ATR's & any others			ATR.	

Overall Rating:

Satisfactory(S)	"5"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

ક્રમાં ટા) | ગ (Signature)

NAME: Sanjeev Kumar Paswan
J.E, RWD, Terhagachh