

FIELD INSPECTION REPORT


Date of Inspection : 20-01-2021	District: East Champaran
Division : Boeraj	Length (km):
Name of the Road: SH-70 Mathi to Upadhyaytola	
Scheme/Programme: MAINTENANCE	PMUSY
Package No.:	Road Id No.: PMUSY 31708302031
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes Yes/No
g)	Compaction of flank/slope & raincuts if any	No Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	No Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Letters have been issued to constructor.


 20.01.20
 (Signature)

NAME: Mahendra Kumar

DESIGNATION: A-E

R. W. D. Boeraj

Scanned with CamScanner

Scanned by TapScanner